



Final Report

Estimate No. : **b1 63322**
 Date Estimated : **15/09/2022**
 Prepared By : **Jack Ng Guo Ming**

Page No. :

- **ESTIMATE REPAIR FOR -**
Trinity Construction Development Pt
2 Venture Drive
#10-08 Vision Exchange

- **ACCOUNT - 136**
Ergo Insurance Pte Ltd
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

Singapore 608526

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SMT6430T	WBAJR12030CE36479	09/07/2020	520i	36800

DESCRIPTION	ORIGINAL PRICE		NETT
To replace front bumper include knocking out dents caused by the accident	850.00	0.00	850.00
To respray front bumper.	986.00	0.00	986.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function	168.00	0.00	168.00
To check electrical wiring system at the front section for proper function	168.00	0.00	168.00
* To replace LH high intensity headlight include functionality programming and conducting checks for proper function	457.00	0.00	457.00 ✓ (supp)
Sundries	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER PANEL PRIMED (PMA/PDC)	1,454.15	1.00	0.00	1,454.15
LH HEADLIGHT LED AHL HIGH (ICON LIGHT)	4,960.90	1.00	0.00	4,960.90

SUPPLEMENTARY ITEMS

Total Labour :	2,709.00
Total Parts :	6,415.05
Total Labour & Parts :	9,124.05
Deduction for Excess :	700.00
Total Repair Costs less Excess:	8,424.05
GST @7%:	589.68
Grand Total :	9,013.73

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

