

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

20/09/2022

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 08/07/2022

Estimated repair cost for vehicle no: SKP3526R TOTOTA COROLLA ALTIS1.6 AUTO

CHASSIS: MR053ZEE106159628 (2009)

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Painted</i>	\$586.30	\$586.30 ✓
2	1	FRONT BUMPER REINFORCEMENT <i>new</i>	\$486.30	\$486.30 x
3	2	FRONT BUMPER SIDE RETAINER <i>Painted</i>	\$75.40	\$150.80 <i>38</i>
4	1	FRONT BUMPER FOG LAMP <i>Painted</i>	\$254.10	\$254.10 ✓
5	1	FRONT BUMPER FOG LAMP OUTER GARNISH <i>new</i>	\$85.40	\$85.40 x
6	1	FRONT SUPPORT PANEL <i>new</i>	\$980.30	\$980.30 x
7	1	FRONT HEADLAMP <i>cut</i>	\$781.20	\$781.20 ✓
8	1	FRONT FENDER <i>green</i>	\$650.10	\$650.10 +
9	1	FRONT FENDER EMBLEM VVTI	\$49.20	\$49.20 x

1659.60

1244.70

TOTAL : \$4,023.70

LESS 25 % \$1,005.93

SUB-TOTAL : \$3,017.78

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 <i>40</i>
2	1	FRONT GRILLE CLIPS <i>new</i>	\$50.00	\$50.00 x

40

TOTAL: \$130.00

TOTAL PARTS \$3,147.78

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS

\$600.00 *300*

\$600.00 *250*

\$80.00 *50*

\$150.00 x

Subtotal :- \$1,430.00

Total:- \$4,577.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1864.70

h/s : 1.5/c

(1.5k)

Adrian Li

h/s 21/09/22

02 Days