



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 3159U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	WINDSCREEN MOULDING	NECESSARY	133.00	133.00
1	TAIL GATE	BENT	1,193.80	1,193.80
1	REAR BUMPER	BENT	1,150.60	1,150.60
1	REAR END PANEL	TO REPAIR SEE LABOUR	585.00	-
1	TOWING COVER	DENTED	19.30	19.30
1	INNER HANDLE	DENTED	35.00	35.00
1	END PANEL TOP COVER	DENTED	162.80	162.80
	LESS 20% DISCOUNT		-655.90	-538.90
			2,623.60	2,155.60
	<u>NETT ITEMS</u>			
1	SHUTTLE EMBLEM (N)	NECESSARY	55.00	55.00
1	HYBRID EMBLE (N)	NECESSARY	76.00	76.00
1	HONDA LOGO (N)	NECESSARY	65.00	65.00
	LESS 20% DISCOUNT		-	-39.20
			196.00	156.80
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	28.00	28.00
1	PARKING SENSOR (SN)	SHORTED	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
			268.00	268.00
	<u>LABOUR</u>			
	TO REMOVE ALL DAMAGED PARTS ,KNOCK OUT DENTS,JACK OUT DAMAGED PANEL PANEL,ADJUST ,REPLACE ,RESHAPE ,CUT,WELD ,REFIX & REALIGN BODY STRUCTURE.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,500.00	600.00
	SPRAY PAINTING FOR NEW AND REPAIR PARTS INCLUDING SUPPLY OF PAINTS MATERIALS.		1,200.00	660.00
	TO TRANSFER TAIL GATE MECHANISM & ATTACHMENT FROM OLD TO NEW .		100.00	60.00
	TO CHECK WIRING FOR PROPER FUNCTION .		50.00	20.00

Report Ref No. CS/AGI22009160/Kvy3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REFIX REAR WINDSCREEN TO FACILITATE REPAIR.		150.00	120.00
	CAVITY PRESERVATION ON ALL AFFECTED AREAS .		120.00	60.00
			3,120.00	1,520.00
GRAND TOTAL			6,207.60	4,100.40
RECOMMENDED COST OF REPAIRS				4,100.40

Report Ref No. CS/AGI22009160/Kvy3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.