

ASS. REC. BY:

REF:

AGW 220091601KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

1.81

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SIR 3159U

Yr Regn:

08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

c.c

1496

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

122322

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP7 1116296

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

15/9/12

D.O.I.

19/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/9

Unable to locate 7nd parts, I.B.I.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

F. P. S

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047
Tel : 64810304 Fax : 64815587 Reg No : 200600989K

Budgetdirect

Motorcar Claim Department
Attn Officer In Charge

Estimate Repair

Date : 19/09/2022

Accident Involving SLR3159U & SLE1007G On 15/9/2022

(1/2)

Item	Descriptions	Amount	
1	Tail Gate	\$ 1,193.80	✓
2	Windsreen Moulding	\$ 133.00	✓
3	Rear Bumper	\$ 1,150.60	✓
4	Rear End Panel	\$ 585.00	✓
5	Towing Cover	\$ 19.30	✓
Total For Parts (Less 20%)		\$ 3,081.70	

S/N Item (s)			
1	Rear Bumper Clips - 1 Set	\$ 28.00	✓
2	Parking Sensor	\$ 200.00	✓
3	Shuttle Emblem	\$ 55.00	✓
4	HYBRID Emble	\$ 76.00	✓
5	HONDA Logo	\$ 65.00	✓
6	Rear Windscreen Sealant	\$ 40.00	✓
Total For S/N		\$ 464.00	

Labour & Misc

1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel	\$ 1,500.00	600l
	Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ 1,200.00	600l
2	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ 100.00	60l
3	To Transfer Tail Gate Mechanism & Attachment From Old To New	\$ 50.00	20l
4	To Check Wiring For Proper Function	\$ 150.00	120l
5	Remove & Refix Rear Windscreen To Facilitate Repair	\$ 120.00	60l
11	Cavity Preservation On All Affected Areas		

Supplementary ① inner handle. n.a #35. ✓

② End Panel Top Cover. #162.80 n.a

Total For Parts & Labour \$ 6,665.70

Ready Auto Care Pte Ltd

Sulynn - 64810304

No Of Days For Repair 5 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer