

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

19-Sep-22

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1540 K

| | | | | |
|-------|---|----|----------|---------|
| 1 pc | Rear bumper | \$ | 459.40 | de |
| 1 pc | Rear bumper reinforcement | \$ | 294.80 | X |
| 2 pcs | Rear bumper reinforcement n/s & o/s lower bracket | \$ | 20.00 | X |
| 1 pc | Rear bumper reinforcement centre lower bracket | \$ | 15.00 | X |
| 2 pcs | Rear bumper n/s & o/s stay | \$ | 276.20 | X |
| 2 pcs | Rear bumper n/s & o/s side bracket | \$ | 66.20 | X |
| 1 pc | Rear bumper lower moulding centre | \$ | 216.50 | ant |
| 1 pc | Rear bumper lower cover | \$ | 47.50 | X un |
| 1 pc | Rear bumper cap hook | \$ | 9.10 | X un |
| 2 pcs | Rear bumper n/s & o/s reflector @ \$31.90 | \$ | 63.80 | o/s ant |
| | | \$ | 1,468.50 | 31.90 |
| | | \$ | 293.70 | 707.80 |
| | | \$ | 1,174.80 | 637.02 |

Less 20%

S/Nett

| | |
|-------|-------------------------------|
| 1 set | Rear bumper clips |
| 1 set | Reverse sensor |
| 1 set | End panel inner garnish clips |
| 1 pc | Rear o/s fender sticker |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sundry

To check wiring

To dismantle / replace reverse sensor to new bumper and reset to the same

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, rear bumper, rear o/s fender, etc

To putty and spray painting on rear bumper, end panel, rear bumper lower centre moulding (Silver), rear bumper lower cover (Silver), rear o/s fender

To apply rustproofing on the repaired and replaced panels.

| | | |
|----|--------|-------|
| \$ | 48.00 | 3 one |
| \$ | 280.00 | X |
| \$ | 38.00 | X |
| \$ | 60.00 | X |
| \$ | 50.00 | X un |
| \$ | 50.00 | X un |

\$ 120.00 30

\$ 180.00 X un

\$ 1,000.00 200

\$ 1,000.00 300

\$ 120.00 X un

\$ 4,120.80 530

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanpin 97455789
wp 16/9/22 C44Jpm
LB Kozing after repair
fender @ 1/11/22
2 days