

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 19 Sep 2022

Preliminary Advice

Vehicle No	: SGU121R	Accident Date	: 16/09/2022
Make	: TOYOTA CAMRY	Policy No.	: SP2000575096-01
Assignment Date	: 19/09/2022	Excess	: S\$600.00
Date of Inspection	: 19/09/2022	Est. Duration of Repair	: 5
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (SIN MING) 176 SIN MING DRIVE #01-06, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,301.80
Revised Amount	:S\$	3,831.80
Check Items (Estimated)	:S\$	1,463.00
Total	:S\$	5,294.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	33,000.00
COE / PARF Rebate	:S\$	11,896.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,104.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :the vehicle repair on part by parts basis.due to no 2nd hand parts available.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.