

ASS. REC. BY:

REF:

AIS/ 22009166/Knc

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

600 ?

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

833K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SGU 121R

Yr Regn:

10, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Camry

c.c

1998

Colour

h.p. White

A/C:

Insured / Std / NI / NA

Sp. Reading

151071

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR053BK 4107057387

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/55R 17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

16/9/22

D.O.I.

19/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

1 Wksp asking for part by part as unable to locate 2nd parts for Camry
3/10 84294.80 Camry (Red, 2052, 32%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1) 13/10/22

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

4294.80



INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2000575096-01	Date of Loss:	16/09/2022
Vehicle Reg. No.:	SGU121R	Driveable?	
Driver Age/Info:	53 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MUHAMAD MURAD BIN KASMANI	Contact No:	+6591278940
Driver:	MUHAMAD MURAD BIN KASMANI		
Make/Model:	TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Vehicle Reg. Date:	29/10/2010
Vehicle Colour:	WHITE	Chassis No:	MR053BK4107057387
Engine No:	1AZE170408		
Odometer:	1 KM		
Paint Type:			<i>Not Notified</i>
Total Loss?	NO		<i>\$ 4294.80</i>
Est. Duration of Repair (day)	<i>10 5 days</i>		<i>Recovery After Repair</i>
			<i>EXCESS TBA</i>
Description of Accident/Loss	REFER TO SAS REPORT.		
Remarks:	VEHICLE IS IN SIN MING W/SHOP.		
Present Location:	PLEASE ARRANGE FOR VEHICLE SURVEY. FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)		

COST OF CLAIMS

	Amount
Parts	3,951.80
Miscellaneous Items	0.00
Labour	2,350.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,301.80
+ GST 7.00% (S\$)	441.13
Nett Amount (S\$)	6,742.93

This claim is handled by: ANDY

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Sep 2022)
Parts: 143 TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Falcon-Air Auto Services Pte Ltd/SGU121R/17/09/2022 11:36
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Bonnet 450	0.00	0.00	Ry *450.00 F	✓
2	1		*Bonnet Lock	0.00	0.00	R *70.00 F	X
3	1		*Brace Panel 50	0.00	0.00	Ry *50.00 F	✓
4	1		*LH HeadLamp 360	0.00	0.00	ngm *360.00 F	✓
5	1		*RH HeadLamp 360	0.00	0.00	u *360.00 F	✓
6	1		*Front Grille 180	0.00	0.00	cm *180.00 F	✓
7	1		*Front Grille Logo 28	0.00	0.00	ru *28.00 F	✓
8	1		*Radiator	0.00	0.00	pu *550.00 F	X
9	1		*Radiator Support Panel	0.00	0.00	R *330.00 F	X
10	1		*Front Bumper 263	0.00	0.00	cm *265.00 F	✓
11	1		*Front Bumper Reinforcement 170	0.00	0.00	Ry *170.00 F	✓
12	1		*Front Bumper Sponge 75	0.00	0.00	cm *75.00 F	✓
13	1		*LH Front Bumper Side Retainer 40	0.00	0.00	diy *40.00 F	✓
14	1		*RH Front Bumper Side Retainer 40	0.00	0.00	diy *40.00 F	✓
15	1		*Front Bumper Lower Grille	0.00	0.00	pu *70.00 F	X
16	1		*Air Con Condenser 380	pu 0.00	0.00	*380.00 F	X
17	1		*Front Bumper Clip	0	0.00	ru *60.00 FS	✓
18	1		*LH Air Guide 60	0.00	0.00	diy *60.00 F	✓
19	1		*RH Air Guide 60	0.00	0.00	diy *60.00 F	✓
F=Franchise part. S=SpcNett.							
RM No plate 455N mis ✓						Sub Total (S\$)	3,598.00
						+ Margin on L,N Items 10.00% (S\$)	353.80
						Total Parts (S\$)	3,951.80

Falcon-Air Auto Services Pte Ltd/SGU121R/17/09/2022 11:36. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To check wiring and focus headlamp	New	50.00 <i>200</i>
2	To vacuum, re-oil and re-gas air con	New	120.00 <i>100</i>
3	To cut out/re-weld radiator support panel, repair front chassis, front fenders including replacement of parts	New	880.00 <i>500</i>
4	To spray paint on bonnet, front bumper, radiator support panel, LH/RH front fender	New	1,300.00 <i>800</i>
Gross Labour Cost (\$\$)			2,350.00

Falcon-Air Auto Services Pte Ltd/SGU121R/17/09/2022 11:36. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 724I

Vehicle Details

Vehicle No.: SGU121R

Vehicle to be Exported: No

Intended Deregistration Date: 17 Sep 2022

Vehicle Make: TOYOTA

Vehicle Model: CAMRY 2.0 AUTO ABS AIRBAG

Primary Colour: White

Manufacturing Year: 2010

Engine No.: 1AZE170408

Chassis No.: MR053BK4107057387

Maximum Power Output: 108.0 kW (144 bhp)

Open Market Value: \$26,443.00

Original Registration Date: 29 Oct 2010

First Registration Date: 29 Oct 2010

Transfer Count: 3

Actual ARF Paid: \$26,443.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 28 Oct 2025

COE Category: E - Open Category

COE Period(Years): 5

PQP Paid: \$19,108.00

COE Rebate Amount: \$11,896.00

Total Rebate Amount: \$11,896.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Sep 2022

OK