

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0797/2022/EQ
DATE : 14-Sep-22
WIP : 41834

Xiao Chun .

05 Days .

\$ 3454.40

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/09/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHUA BAN LEE (CAI WANLI)
ADDRESS : BLK 235 CHOA CHU KANG CENTRAL
#09-21
SINGAPORE 680235
TELEPHONE : HP +65 82223337
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900088959-01
VEHICLE NO : **SML 3337 S**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 23/4/2019
ENGINE NO : CVK 077150
CHASSIS NO : WAUZZZF48KA042003
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Sep-22
PLACE OF ACCIDENT : CHOA CHU KANG ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 3337 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER AND RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	500 ✓
3	TO RESPRAY REAR BUMPER, RHS REAR FENDER AND RHS REAR DOOR.	\$	2,800.00	1100 ✓
4	TO RENEW RHS REAR RIM AND CARRY OUT DIAGNOSTIC CHECK.	S/N \$	280.00	✓
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 6,032.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 3337 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Regis</i>	1	\$ 3,188.00	<i>X</i>
2	REAR BUMPER FIXING PARTS <i>2</i>	1	\$ 487.00	<i>+</i>
3	REAR BUMPER SECURING STRIP <i>2</i>	1	\$ 249.00	<i>+</i>
4	REAR BUMPER SPOILER <i>he a</i>	1	\$ 276.00	<i>+</i>
5	REAR BUMPER BRACKET - RH	1	\$ 130.00	<i>+</i>
6	REAR BUMPER REFLECTOR - RH <i>2</i>	1	\$ 46.00	<i>+</i>
7	REAR BUMPER LOWER GUIDE SECTION - RH <i>he a</i>	1	\$ 26.00	<i>+</i>
8	REAR BUMPER HOLDING STRAP - RH	1	\$ 94.00	<i>+</i>
9	REAR BUMPER UPPER GUIDE SECTION - RH	1	\$ 51.00	<i>+</i>
10	REAR ALUMINIUM RIM <i>ct</i>	1	\$ 1,278.00	<i>✓</i> 1022.40
11	REAR ALUMINIUM RIM RUBBER VALVE <i>he a</i>	1	\$ 4.00	<i>+</i>
12	SUNDRIES <i>the new</i>		\$ 300.00	<i>7X</i>
TOTAL SPARE PARTS		:	\$ 6,129.00	
TOTAL LABOUR CHARGES		:	\$ 6,032.00	
GRAND TOTAL		:	\$ 12,161.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

Adrian G
16/09/22

Not Authorised, 05 Rps 

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT