

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0797/2022/EQ  
**DATE** : 14-Sep-22  
**WIP** : 41834

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/09/2022**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

*Hi Adrian  
5 days - ok - Johnny Boo  
11-Nov-22*

**OWNER'S NAME** : MR CHUA BAN LEE (CAI WANLI)  
**ADDRESS** : BLK 235 CHOA CHU KANG CENTRAL  
#09-21  
SINGAPORE 680235  
**TELEPHONE** : HP +65 82223337  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 1900088959-01  
**VEHICLE NO** : **SML 3337 S**  
**MODEL CODE** : AUDI A4 SEDAN 2.0 TFSI 8W  
**MODEL YEAR** : 23/4/2019  
**ENGINE NO** : CVK 077150  
**CHASSIS NO** : WAUZZZF48KA042003  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 12-Sep-22  
**PLACE OF ACCIDENT** : CHOA CHU KANG ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

### **ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 3337 S**

| S/N                         | NATURE OF JOBS                                                                                                                                         |        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-------------------------------|
| 1                           | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.                                                                                      | S/N \$ | 360.00               | \$ <b>360.00</b>              |
| 2                           | TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER AND RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$     | 2,400.00             | \$ <b>500.00</b>              |
| 3                           | TO RESPRAY REAR BUMPER, RHS REAR FENDER AND RHS REAR DOOR.                                                                                             | \$     | 2,800.00             | \$ <b>1,100.00</b>            |
| 4                           | TO RENEW RHS REAR RIM AND CARRY OUT DIAGNOSTIC CHECK.                                                                                                  | S/N \$ | 280.00               | \$ <b>280.00</b>              |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                                          | S/N \$ | 192.00               | \$ <b>192.00</b>              |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                        | :      | <b>\$ 6,032.00</b>   | <b>\$ 2,432.00</b>            |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 3337 S**

|                             |                                      |            | <b>DAMAGED PARTS &amp; PRICES</b> |                    |
|-----------------------------|--------------------------------------|------------|-----------------------------------|--------------------|
| <b>S/N</b>                  | <b>PARTS DESCRIPTION</b>             | <b>QTY</b> | <b>S/NETT</b>                     | <b>REMARKS</b>     |
| 1                           | REAR BUMPER                          | 1          | \$ 3,188.00                       |                    |
| 2                           | REAR BUMPER FIXING PARTS             | 1          | \$ 487.00                         |                    |
| 3                           | REAR BUMPER SECURING STRIP           | 1          | \$ 249.00                         |                    |
| 4                           | REAR BUMPER SPOILER                  | 1          | \$ 276.00                         |                    |
| 5                           | REAR BUMPER BRACKET - RH             | 1          | \$ 130.00                         |                    |
| 6                           | REAR BUMPER REFLECTOR - RH           | 1          | \$ 46.00                          |                    |
| 7                           | REAR BUMPER LOWER GUIDE SECTION - RH | 1          | \$ 26.00                          |                    |
| 8                           | REAR BUMPER HOLDING STRAP - RH       | 1          | \$ 94.00                          |                    |
| 9                           | REAR BUMPER UPPER GUIDE SECTION - RH | 1          | \$ 51.00                          |                    |
| 10                          | REAR ALUMINIUM RIM                   | 1          | \$ 1,278.00                       | \$ <b>1,022.40</b> |
| 11                          | REAR ALUMINIUM RIM RUBBER VALVE      | 1          | \$ 4.00                           |                    |
| 12                          | SUNDRIES                             |            | \$ 300.00                         |                    |
| <b>TOTAL SPARE PARTS</b>    |                                      |            | <b>\$ 6,129.00</b>                | <b>\$ 1,022.40</b> |
| <b>TOTAL LABOUR CHARGES</b> |                                      |            | <b>\$ 6,032.00</b>                | <b>\$ 2,432.00</b> |
| <b>GRAND TOTAL</b>          |                                      |            | <b>\$ 12,161.00</b>               | <b>\$ 3,454.40</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.  
 BL-28/10/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT