

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wenyo

Date: 17 Oct 2022

Preliminary Advice

Insured Vehicle No	: SGN3547S	Accident Date	: 16/09/2022
TP Vehicle No	: SJZ9281R	Assignment Date	: 19/09/2022
Make	: NISSAN NOTE	Est. Duration of Repair	: 8
Date of Inspection	: 19/09/2022		
Inspection At	: MIRAGE MOTORWERKZ PTE LTD (HQ) 10 KAKI BUKIT ROAD 2 #01-29 FIRST EAST CENTRE SINGAPORE 417868		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,042.22
Revised Amount	:S\$	10,051.75
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,051.75
 Lump Sum Repair	 :S\$	 8,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (x) Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.