



Case Details

Case Reference Number : TAX/09/22/2033
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5320M

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-19374-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : income insurance limited
 Accident Date and Time : 14/09/2022 03:20 PM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER FRT	1	602.60	602.60	25.00	451.95	Replace	1	451.95	Replace	✓ BR
One Time Key In	Main			BUMPER CLIPS (10 PCS)	10	4.80	48.00	25.00	36.00	Replace	10	36.00	Replace	✓ MEC
One Time Key In	Main			BUMPER SUPPORT F/LH	1	86.20	86.20	25.00	64.65	Replace	1	64.65	Replace	✓ BR
One Time Key In	Main			FOG LAMP LH	1	319.30	319.30	10.00	287.37	Replace	0	0	Not Give	X NR
One Time Key In	Main			LENS & BODY,FR TURN LH	1	581.40	581.40	10.00	523.26	Replace	1	523.26	Replace	✓ SQR
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	32.40	32.40	25.00	24.30	Replace	0	0	Not Give	X
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	76.60	76.60	25.00	57.45	Replace	0	0	Not Give	X NR
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	34.50	34.50	25.00	25.88	Replace	0	0	Not Give	X
One Time Key In	Main			HEAD LAMP LH	1	1,075.40	1,075.40	10.00	967.86	Replace	1	967.86	Replace	✓ ART
One Time Key In	Main			MIRROR ASSY,LH	1	1,399.60	1,399.60	10.00	1,259.64	Replace	0	0	Not Give	X NA

Total Spare Part Cost 9,382.13

Surveyor Total 2,988.31

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20.00

Final Spare Part Cost 7,505.70

Final Sur Total 2,390.65

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MIRROR LAMP LH	1	73.80	73.80	10.00	66.42	Replace	1	66.42	Replace	✓ Lt
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	142.30	142.30	25.00	106.73	Replace	1	0	Repair	x Rpmi
One Time Key In	Main			FENDER FRT/LH	1	916.30	916.30	25.00	687.22	Replace	1	687.22	Replace	✓ Bue
One Time Key In	Main			NAME PLATE (HYBRID)	1	59.20	59.20	25.00	44.40	Replace	1	44.40	Replace	✓ ntc
One Time Key In	Main			FENDER PROTECTOR FRT/LH UPPER	1	52.60	52.60	25.00	39.45	Replace	0	0	Not Give	x
One Time Key In	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	130.50	130.50	25.00	97.88	Replace	0	0	Not Give	x } an
One Time Key In	Main			SEAL, FRONT FENDER TO COWL SIDE LH	1	17.50	17.50	25.00	13.13	Replace	0	0	Not Give	x
One Time Key In	Main			FENDER LINER FRT/LH	1	195.40	195.40	25.00	146.55	Replace	1	146.55	Replace	✓ TN
One Time Key In	Main			FENDER LINER PAD, FR WHEEL LH	1	56.30	56.30	25.00	42.22	Replace	0	0	Not Give	x } an
One Time Key In	Main			FENDER APRON SUB FRT/LH	1	724.00	724.00	25.00	543.00	Replace	0	0	Not Give	x } an
One Time Key In	Main			WHEEL DISC, FRONT	1	1,978.60	1,978.60	25.00	1,483.95	Replace	1	0	Repair	x Rpmi
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	x an
One Time Key In	Main			SHOCK ABSORBER FRT/LH	1	475.80	475.80	25.00	356.85	Replace	0	0	Check	?
One Time Key In	Main			LOWER ARM FRT/LH	1	823.20	823.20	25.00	617.40	Replace	0	0	Check	?
One Time Key In	Main			WHEEL HUB FRT	1	722.10	722.10	25.00	541.58	Replace	0	0	Check	?
Total Spare Part Cost									9,382.13	Surveyor Total		2,988.31		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20.00		
Final Spare Part Cost									7,505.70	Final Sur Total		2,390.65		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			STEERING KNUCKLE LH FRT	1	764.30	764.30	25.00	573.22	Replace	0	0	Check	✓ ?
One Time Key In	Main			UNDER COVER SIDE/LH	1	52.50	52.50	25.00	39.38	Replace	0	0	Not Give	✓ X
One Time Key In	Main			TIE ROD END LH	1	210.20	210.20	25.00	157.65	Replace	0	0	Not Give	✓ X
Total Spare Part Cost									9,382.13	Surveyor Total			2,988.31	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20.00	
Final Spare Part Cost									7,505.70	Final Sur Total			2,390.65	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	1,014.00	400.00	/
Total:			1,014.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200.00	/
2	Main	TO RESPRAY FRONT FENDER LH	378.00	200.00	/
3	Main	TO RESPRAY VIEW MIRROR	180.00	100.00	/
4	Main	TO RESPRAY RIM	180.00	100.00	/
5	Main	TO RESPRAY APRON PANEL LH	180.00	0	XNN
Total:			1,296.00	600.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0	X request invoice
2	Main	TO WASH AND VACUUM	40.00	0	X
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	30.00	/
Total:			556.00	150.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60.00	/
5	Main	TO DO WHEEL ALIGNMENT TYRE BALANCING	120.00	60.00	/
6	Main	TO REPLACE SUNDRY PARTS	100.00	0	XNN
Total:			556.00	150.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	7,505.70	2,390.65
Total Labour Cost	1,014.00	400.00
Total Spray Painting	1,296.00	600.00
Other	556.00	150.00
Overall Total	10,371.70	3,540.65
Lump Sum Repair Option		☒
Lump Sum Total	10,350.00	3,550.00
Surveyor Approved Amount		3,550.00
No of Repair Days*	6	5 ✓
Remarks	-	REQUEST NBV / LUMP SUM REPAIR / AFTER PAINT PPHOTOS / FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR NUMBER 92418544
Surveyor Name		GuoQiang
Signature		
Survey Date	16/09/2022	Save Clear

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: