



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22005709/Tvy3e2-1	
			Date: 03/10/2022	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 3072S	Veh. Inspected	FBS 7501B
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/22/22/VC05/025873	Excess (\$)	0.00
	Assign From	ENG HUEY NI	Assign Date	17/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA XSR155	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	MH3RG4760MK020749	Colour	BLACK
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/70 R17	BRIDGESTONE	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	140/70 R17	BRIDGESTONE	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S, O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	31/05/2022	Inspection Date	16/06/2022
	Survey held at	KIM HENG SENG MOTOR BLK 9002 TAMPINES STREET 93 #01-16 SINGAPORE 528836		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	