

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2209-501-TG

DATE : 19-Sep-2022

POLICY NO. :

VEHICLE REG. NO. : SMG6308H

VEHICLE MAKE : HONDA CITY 1.5 V CVT

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper X	1	\$ 509.80	\$ 509.80
2	Front Bumper Side Retainer RH X	1	\$ 31.40	\$ 31.40
3	Front Fender RH / DD	1	\$ 393.80	\$ 393.80
4	Front Fender Innershield RH	1	\$ 96.50	\$ 96.50
5	Front Door RH / DD	1	\$ 788.40	\$ 788.40
6	Front Door Hinge Upper RH X	1	\$ 76.80	\$ 76.80
7	Front Door Hinge Lower RH X	1	\$ 78.40	\$ 78.40
8	Front Headlamp RH X	1	\$ 695.70	\$ 695.70
9	Front Rim RH / CVT	1	\$ 640.20	\$ 640.20
10	Front Wheel Bearing RH X	1	\$ 173.50	\$ 173.50
11	Front Wheel Hub RH X	1	\$ 188.20	\$ 188.20
12	Front Lower Arm RH X	1	\$ 210.30	\$ 210.30
13	Front Knuckle Arm RH X	1	\$ 246.70	\$ 246.70
14	Front Shock Absorber RH X	1	\$ 381.20	\$ 381.20
15	Front Shock Absorber Mounting RH X	1	\$ 55.80	\$ 55.80
16	Front Tie Rod End RH X	1	\$ 91.80	\$ 91.80
17	Front Stabilizer Linkage RH X	1	\$ 69.80	\$ 69.80
Part Less 20%				\$ (945.66)
Total Spare Parts				\$ 3,782.64
SPECIAL NETT				
18	Front Bumper Clips X	10	\$ 5.00	\$ 50.00
19	Front Fender Innershield Clips .7	10	\$ 5.00	\$ 50.00
Total Special Nett				\$ 100.00
LABOUR				
20	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 1,000.00	\$ 1,000.00 700
21	Spray Paint (Front Bumper, Front Fender RH, Front Door RH, Rocker Panel RH)	1	\$ 1,000.00	\$ 1,000.00 800
23	To Perform 4 Wheel Alignment	1	\$ 70.00	\$ 70.00 ✓
24	Remove, Refit and Replace Front Undercarriage RH	1	\$ 180.00	\$ 180.00 X
25	Transfer door fitting and window mechanism to new door	1	\$ 80.00	\$ 80.00 50
26	Check and Rectify Electrical Wiring	1	\$ 50.00	\$ 50.00 30
Total Labour				\$ 2,380.00

Estimate prepared by: James Tan

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2209-501-TG
DATE : 19-Sep-2022
POLICY NO. :
VEHICLE REG. NO. : **SMG6308H**
VEHICLE MAKE : HONDA CITY 1.5 V CVTTO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.			Amount Before Excess	\$ 6,262.64
			Add GST @ 7%	438.38
			Total Amount Payable	\$ 6,701.02

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: