

ARC

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2209-501-TG

DATE : 19-Sep-2022

POLICY NO. :

VEHICLE REG. NO. : SMG6308H

VEHICLE MAKE : HONDA CITY 1.5 V CVT

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper <i>X R 1 / BR</i>	1	\$ 509.80	\$ 509.80 ✓
2	Front BumperSide Retainer RH <i>X nn</i>	1	\$ 31.40	\$ 31.40 ✓
3	Front Fender RH <i>/ nn</i>	1	\$ 393.80	\$ 393.80 ✓
4	Front Fender Innershield RH <i>/ X nn</i>	1	\$ 96.50	\$ 96.50 ✓
5	Front Fender Innershield RH <i>/ X nn</i>	1	\$ 788.40	\$ 788.40 ✓
6	Front Door RH <i>/ nn</i>	1	\$ 76.80	\$ 76.80
7	Front Door Hinge Upper RH <i>X nn</i>	1	\$ 78.40	\$ 78.40
8	Front Door Hinge Lower RH <i>X nn</i>	1	\$ 695.70	\$ 695.70 ✓
9	Front Headlamp RH <i>X nn</i>	1	\$ 640.20	\$ 640.20 ✓
10	Front Rim RH <i>/ nn</i>	1	\$ 173.50	\$ 173.50
11	Front Wheel Bearing RH <i>X nn</i>	1	\$ 173.50	\$ 173.50
12	Front Wheel Hub RH <i>X nn</i>	1	\$ 188.20	\$ 188.20
13	Front Lower Arm RH <i>X nn</i>	1	\$ 210.30	\$ 210.30
14	Front Knuckle Arm RH <i>X nn</i>	1	\$ 246.70	\$ 246.70
15	Front Shock Absorber RH <i>X nn</i>	1	\$ 381.20	\$ 381.20
16	Front Shock Absorber Mounting RH <i>X nn</i>	1	\$ 55.80	\$ 55.80
17	Front Tie Rod End RH <i>X nn</i>	1	\$ 91.80	\$ 91.80
18	Front Stabilizer Linkage RH <i>X nn</i>	1	\$ 69.80	\$ 69.80
Part Less 20%				\$ (945.66)
Total Spare Parts				\$ 3,782.64
SPECIAL NETT				
18	Front Bumper Clips <i>X / REC</i>	10	\$ 5.00	\$ 50.00
19	Front Fender Innershield Clips <i>/ X nn</i>	10	\$ 5.00	\$ 50.00
Total Special Nett				\$ 100.00
LABOUR				
20	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 1,000.00	\$ 1,000.00
21	Spray Paint (Front Bumper, Front Fender RH, Front Door RH, Rocker Panel RH)	1	\$ 1,000.00	\$ 1,000.00
23	To Perform 4 Wheel Alignment	1	\$ 70.00	\$ 70.00
24	Remove, Refit and Replace Front Undercarriage RH	1	\$ 180.00	\$ 180.00
25	Transfer door fitting and window mechanism to new door	1	\$ 80.00	\$ 80.00
26	Check and Rectify Electrical Wiring	1	\$ 50.00	\$ 50.00
Total Labour				\$ 2,380.00

Estimate prepared by: James Tan

Page 1 of 2

3,545.76

L/SUM \$2,850.00

6DAYS