

A.C.S. REC BY: T. J. SmithREF: CC6/11622009183/T 43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No _____

Claims No _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGW 4461YYr Regn: 2018 / Jan.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota HiluxC.C. 1998Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 49245

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STEZ B39H 60J001111

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235 / 55 R18R: 72

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 27/9/22Survey held at Jim Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Rep. Format: _____

Lump Sum / L.B. / (P) _____

JIN AUTO SERVICES PTE LTD

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62894656 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

27/9/2022

M/S AIG

DEAR SIR

ESTIMATED REPAIR COST FOR VEHICLE SGW4461Y

		LIST PRICE
1	1PC REAR RH DOOR	\$ 1,650.00 <i>ht</i>
2	1PC REAR RH DOOR LOWER CHROME PROTECTOR	\$ 185.00 <i>cm</i>
3	1PC REAR RH DOOR WINDOW GLASS CHROME GARNISH	\$ -
4	1PC REAR RH DOOR TRIM BOARD	\$ 1,180.00 <i>T</i>
5	1PC REAR RH DOOR HINGE - UPPER	\$ 17.00 <i>R</i>
6	1PC REAR RH DOOR HINGE - LOWER	\$ 81.20 <i>R</i>
7	1PC REAR RH DOOR POWER WINDOW REGULATOR MOTOR	\$ 996.60 <i>T</i>
8	1PC REAR RH DOOR POWER WINDOW REGULATOR (6080242050)	\$ 210.00 <i>T</i>
9	1PC REAR RH DOOR WEATHERSTRIP RUBBER	\$ 181.60 <i>T</i>
10	1PC REAR RH DOOR CHECK	\$ 239.10 <i>K</i>
		<u>\$ 4,740.50</u>
	LESS 25%	\$ (1,185.13)
		<u>\$ 3,555.38</u>
11	LABOUR CHARGES	\$ 600.00 <i>250</i>
12	CHECK WIRING FUNCTIONS TRANSFER DOOR FITTING	\$ 150.00 <i>60</i>
13	PUTTY, APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS	\$ 800.00 <i>350</i>
		<u>\$ 5,105.38</u>

Tayfkm 97495749/62583561
WP' 27/9/22 @ 430pm
p/p Resurvey before paint.
Tayfkm C/ha auto.com
- 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: