

Trans-cab Auto Services Pte Ltd**AAD2209-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD613R

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD613R

VF1ABL15AUC283403

200303878K

RENAULT

LATITUDE

15/09/2022

SNA5454U/AIG

24/11/2017

PART	LIST
1 BUMPER COVER REAR / <i>Re</i>	\$ 561.70
1 BUMPER LOWER REAR / <i>Cat</i>	\$ 411.90
1 BUMPER REFLECTOR RH <i>X</i>	\$ 16.60
1 BUMPER BRACKET CTR REAR <i>X</i>	\$ 98.10
1 BUMPER BRACKET SIDE RH REAR <i>X</i>	\$ 82.10
1 BUMPER RETAINER RH REAR <i>X</i>	\$ 59.80
1 BUMPER BEAM REAR <i>?</i>	\$ 547.80
1 BUMPER BEAM BRACKET LH REAR <i>X</i>	\$ 114.50
1 BUMPER BEAM BRACKET RH REAR <i>X</i>	\$ 114.50
1 OUTER PANEL REAR (End Panel) <i>X</i>	\$ 745.80
1 OUTER PANEL REAR (End Panel)TRIM <i>?</i>	\$ 404.56
1 BOOT REAR / <i>BT</i>	\$ 1,677.20
1 BOOT LOCK / <i>3m</i>	\$ 246.60
1 BOOT LOCK CATCH <i>X</i>	\$ 41.70
1 BOOT FINISHER <i>X</i>	\$ 344.70
1 BOOT WEATHERSTRIP /	\$ 178.20
1 BOOT STRUT LH <i>X</i>	\$ 145.10
1 BOOT STRUT RH <i>X</i>	\$ 145.10
1 BOOT HINGE LH <i>X</i>	\$ 254.20
1 BOOT HINGE RH <i>X</i>	\$ 254.20
1 BOOT BADGE 'RENAULT' / <i>Mc</i>	\$ 82.40
1 BOOT BADGE / <i>Mc</i>	\$ 95.80
1 TAILLAMP LH <i>X</i>	\$ 401.40

\$ 15,947.26**10% \$ 1,594.73**

Trans-cab Auto Services Pte Ltd**AAD2209-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD613R

\$	14,352.53
----	------------------

Special Nett			
1SET PARKING AID ?		\$	700.00
1SET REAR BUMPER CLIP / MC		\$	66.00
1SET BUMPER BRACKET SIDE CLIP RH RR X	} NN	\$	10.00
1SET BUMPER RETAINER RH CLIP RR X		\$	20.00
1SET BUMPER BRACKET SIDE CLIP LH RR X		\$	10.00
1SET BUMPER RETAINER CLIP LH RR X		\$	20.00
1SET BUMPER LOWER REAR CLIP X		\$	66.00
1 REAR BUMPER ADVERTISEMENT / MC		\$	100.00
2 WINDSCREEN SEALANT X		\$	150.00
1 WINDSCREEN MOULDING X	} NN	\$	200.00
1 WINDSCREEN INNER SPONGE SEAL X		\$	130.00
TOTAL		\$	1,509.82
TOTAL PARTS		\$	15,862.35

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	X NN
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	600
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	400
To Rust-Proofing Of The Affected Areas.	\$	170.00	X NN
To reinstall rear bumper parking sensor.	\$	170.00	40
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X } NN
To repair and realign rear exhaust pipe.	\$	170.00	X }

Trans-cab Auto Services Pte Ltd**AAD2209-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD613R

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	X

TOTAL \$ 7,880.00**Over All Total \$ 38,094.89****(LUMP SUM)****Repair Days****20 DAYS***4 Days.**Lumpsum repair**After repair photo.**Eme Ai ap**8288 0282**16/9/22*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: