



BOON SIEW SINGAPORE PTE LTD

370 Ubi Road 3 Singapore 408651

255 Alexandra Road Singapore 159937

Tel: +65 6339 9002

Website: +65 6333 4332

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LIBERTY INSURANCE PTE LTD
 51 CLUB STREET
 #03-00 LIBERTY HOUSE SINGAPORE
 SINGAPORE 69428

Registration No : FBS3020Z
 Chassis No : JH2NC5695KK000378
 Model : 2019 CB400X GRAND PRIX RED
 Owner's Name : VICKNESHWARAN S/O VEERAPPAN
 Ins Policy No :
 Date of Accident :

Document No. : SQT0000203
 Date : 23. Aug 2022
 Customer No. : 1005
 Svc Advisor :
 Engine No : NC56E5000381
 Date | Time : 23. Aug 2022 5:02:00 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	DATE OF ACCIDENT: 22.08.22						
	POLICY NO.:5121427188-01						
	DATE TOW/DRIVE IN:						
	SURVEYOR NAME:						
	DATE SURVEY:						
	AUTHORISED BY:						
	EXCESS:						
	3RD PARTY VEHICLE NO.: N.A						
	CASE REF.:						
B00016	TOWING FROM 8B ADMIRALTY TO BSS (RECEIPT NO. 10702)	0.9	50.00		45.00	3.15	48.15
070798	TO REMOVE ALL DAMAGED PARTS, NECESSARY ATTACHMENT, REALIGN AFFECTED PORTION TO ALIGNMENT	3	350.00		1050.00	73.50	1123.50
060698	USING HONDA MOTORCYCLE COMMUNICATION SYSTEM (MCS) TO ERASE/RESET MEMORY. NETT	2.4	50.00		120.00	8.40	128.40
WSP010	TOP BOX. NETT	1	300.00		300.00	21.00	321.00
WSP010	HANDPHONE MOUNT. NETT	1	20.00		20.00	1.40	21.40
	Sum Labor				1535.00	107.45	1,642.45
88210-MJE-D40	MIRROR COMP R,BACK	1	90.59		90.59	6.34	96.93
53100-MKP-J80ZA	PIPE, STEERING HANDLE	1	79.50		79.50	5.57	85.07
53104-MJE-D40	WEIGHT,STRG HNDL	1	5.49		5.49	0.38	5.87
53105-MGZ-J80	WEIGHT B, STRG HND	1	7.60		7.60	0.53	8.13
53106-KR3-770	RUBBER A HANDLE	1	2.50		2.50	0.18	2.68
90117-KZZ-900	NUT,SET 6MM	1	5.10		5.10	0.36	5.46
53170-MJW-J01	LEVER ASSY, R HNDL	1	55.28		55.28	3.87	59.15
61110-MKP-K80ZA	SET ILLUS,FR FEND	1	246.30		246.30	17.24	263.54
33400-MKP-K01	WINKER ASSY, R FRONT	1	151.30		151.30	10.59	161.89
46500-KYJ-900	PEDAL COMP,RR BRAKE	1	23.30		23.30	1.63	24.93

Printed on 1/9/2022 1:49:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



BOON SIEW SINGAPORE PTE LTD

370 Ubi Road 3 Singapore 408651

255 Alexandra Road Singapore 159937

Tel: +65 6339 9002

Website: +65 6333 4332

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LIBERTY INSURANCE PTE LTD
51 CLUB STREET
#03-00 LIBERTY HOUSE SINGAPORE
SINGAPORE 69428
Registration No : FBS3020Z
Chassis No : JH2NC5695KK000378
Model : 2019 CB400X GRAND PRIX RED
Owner's Name : VICKNESHWARAN S/O VEERAPPAN
Ins Policy No. :
Date of Accident :

Document No. : SQT0000203
Date : 23. Aug 2022
Customer No. : 1005
Svc Advisor :
Engine No : NC56E5000381
Date | Time : 23. Aug 2022 5:02:00 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
17500-MKP-K80ZA	TANK ASSY,FUEL / DD	1	1025.00		1025.00	71.75	1096.75
17574-MGS-D30	PACKING, BASE (Gasket) - MCL	1	21.30		21.30	1.49	22.79
64350-MKP-J80	COVER ASSY,R FR S / cut	1	16.43		16.43	1.15	17.58
83511-MKP-J80ZC	COVER A,R SIDE / cut	1	46.90		46.90	3.28	50.18
83520-MKP-J80	COVER B ASSY,R SI / cut	1	24.75		24.75	1.73	26.48
64300-MKP-K80ZB	SET ILLUS,L MIDL / CPA	1	270.6				
64340-MKP-K80ZA	SET ILLUSTRATE *TYPE2* / cut	1	112.70		112.70	7.89	120.59
64342-MKP-J80	COWL B,R SIDE COWL / cut	1	12.30		12.30	0.86	13.16
11330-MKP-D80	COVER COMP, RIGHT CRANKCASE / cut	1	104.60		104.60	7.32	111.92
91301-ML7-003	O RING 48.1X3.6 / MCL	1	2.80		2.80	0.20	3.00
91307-035-000	ORING 183 / MCL	1	3.50		3.50	0.25	3.75
18310-MKP-J80	MUFFLER COMP / cut DD	1	564.70		564.70	39.53	604.23
18350-MJW-J00	COVER,MUFFLER / cut	1	92.80		92.80	6.50	99.30
96400-0803504	BOLT,FLANGE DR 8X / MCL	1	0.90		0.90	0.06	0.96
Headlight - cut							
Sum Item					2695.64	188.70	2,884.34

Survey By _____

Date & Time _____

Excess _____

Status _____

Signature _____

Total Amount 4,230.64 296.15 4,526.79

Total (Inclusive of GST) 5069.24 4,526.79

- LKK Auto Consultants hence notify the Repairer of the following:
- To be survey before after spray painting
 - To be spray paint part(s) during resurvey
 - Repairer to provide confirmation
 - The repairer to be on "Without Prejudice" basis
 - No warranty to be provided
 - Surveys and repairs to be resurveyed and is subject to the approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 1/9/2022 1:49:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.