



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BOON SIEW SINGAPORE PTE LTD 370 UBI ROAD 3 SINGAPORE 408651 ON BEHALF OF VICKNESHWARAN S/O VEERAPPAN			Ref: CS/TP22009189/Gvy3e2 Date: 25/11/2022 Code: TP553	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected		FBS 3020Z
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From TOH BW		Assign Date		22/09/2022
2. Vehicle Particulars & Condition				
Make & Model		HONDA CB400XA	c.c	399
Engine No.		HIDDEN	Year of Reg.	2021
Chassis No.		JH2NC5695KK000378	Colour	RED
Odometer		28649 KM	Steering	IN ORDER
Brakes		IN ORDER	Modification	NIL
General		GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/80Z R19	MITAS	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	160/60Z R17	MITAS	6 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/08/2022	Inspection Date	22/09/2022
	Survey held at	BOON SIEW SINGAPORE PTE LTD 370 UBI ROAD 3 SINGAPORE 408651		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	