



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22009195/Avy3e2	
			Date: 13/10/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SDV 8375C	Veh. Inspected	SLM 4609H
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2203317/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	19/09/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	SUBARU FORESTER	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JF1SJ5KC5HG085695	Colour	SILVER
	Odometer	111304 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/55 R18	YOKOHAMA	6 mm
	L/H Front Tyre	225/55 R18	YOKOHAMA	6 mm
	R/H Rear Tyre	225/55 R18	YOKOHAMA	6 mm
	L/H Rear Tyre	225/55 R18	YOKOHAMA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	18/09/2022	Inspection Date	19/09/2022
	Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	