

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

TP Sampo JF1SJ5KCSHG
Veron.

ESTIMATE OF REPAIR

Veh# : SLM4609M

Model: SUBARU FORESTER

Accident Date : 18/9/22

31/5/2017

Location : CTE TOWARDS CITY BEFORE LOR CHAUN

3P: SDV8375C (SOMPO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Delnd</i>	713.04	<i>625</i>	
2	10pcs	Rear bumper clips <i>new</i>		50.00	<i>30</i>
3	1pc	Rear bumper tow cover <i>Delnd</i>	80.00	<i>30</i>	
4	2pcs	Rear bumper screw clips <i>new</i>		20.00	
5	1pc	Rear bumper lower n/s garnish <i>Delnd</i>	<i>130.20</i>	<i>28</i>	
6	1pc	Rear bumper enforcement <i>Best</i>	<i>610.50</i>	<i>396</i>	
7	2pcs	Rear bumper o/s & n/s reflector <i>RT</i>	225.40		
8	2pcs	Rear bumper o/s & n/s retainer <i>new</i>	126.40		
9	1 set	Rear reverse sensor <i>2nd</i>		380.00	<i>200</i>
10	1pc	Rear end panel <i>Delnd</i>	423.04		
11	1pc	Rear end panel inner trim <i>Delnd</i>	136.12		
12	4pcs	Rear end panel inner trim clips <i>new</i>		20.00	
13	1pc	Rear spare wheel tank panel <i>Branded</i>	<i>842.60</i>	<i>691</i>	
14	1pc	Rear tool sponge <i>Delnd</i>	169.20		
15	1pc	Rear exhaust muffler <i>Delnd</i>	868.00		
16	1pc	Rear exhaust tail pipe <i>Delnd</i> <i>Best (Rip)</i>	<i>910.40</i>	<i>200 (SN)</i>	
17	4pcs	Rear exhaust mounting <i>Delnd</i>	<i>160.00</i>	<i>15</i>	
18	2pcs	Rear o/s & n/s tail lamp retainer <i>new</i>	110.40	x	
19	2pcs	Rear o/s & n/s tail lamp <i>new</i>	932.00	x	
20	1pc	Rear boot cover lock (Upper) <i>Delnd</i>	372.36	x	
21	1pc	Rear boot cover lock (Lower) <i>Delnd</i>	79.10	x	
22	1 pc	Front bumper <i>Delnd</i>	713.04	<i>558</i>	
23	10 pcs	Front bumper clips <i>new</i>		30.00	
24	1 pc	Front bumper enforcement <i>Delnd</i>	445.96	<i>288</i>	
25	2 pcs	Front bumper o/s & n/s retainer <i>new</i>	121.60		
26	2 pcs	Front o/s & n/s fog lamp <i>Delnd</i>	840.60	x	
27	2 pcs	Front o/s & n/s fog lamp garnish (Chrome) <i>RT Missing</i>	<i>360.00</i>	<i>180</i>	
28	1 pc	Front support panel <i>Delnd</i>		x	
29	1 pc	Front grille <i>Delnd</i>	<i>751.40</i>	<i>316</i>	
30	1 pc	Front grille emblem <i>new</i>	87.12		
31	6 pcs	Front grille clips <i>new</i>		30.00	
32	2pcs	Front o/s & n/s head lamp <i>Delnd</i>	<i>4,900.60</i>	<i>4,800</i>	

2PCS Front o/s & n/s head lamp bracket *Delnd*

135.2

1pc Front support panel top garnish *Delnd*

102.5

33	1 pc	Front enforcement <i>Repaired</i>	696.50	X	
34	1 pc	Front radiator	1,210.30	X	
35	1 pc	colent		80.00	X
36	1 pc	Front condenser	1,039.00	X	
37	1 pc	Front reg. no. plate <i>Best</i>		45.00	30
38	1 pc	Front reg. no. plate bracket <i>del-d</i>		25.00	-
		<i>1039158</i>	Sub Total:	17,724.88	680.00 0.00
		<i>8313.26</i>	20%	0%	10%
		<i>S/N: 585</i>	After Less %:	14,179.90	680.00 0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.	2,000.00	1400	
2		To spray painting.	1,500.00	1000	
3		To remove & replace rear reverse sensor	50.00	✓	
4		To remove and replace condenser & top up air con gas	140.00	X	
5		To remove and replace front radiator & pressure test	140.00	X	
6		To check for fault code and resetting	280.00	X	
7		To check wiring.	100.00	60	
8		To re seal anti rust.	100.00	✓	
		Sub Total:	4,310.00		
		Total:	19,169.90		
		After Less 20%:	15,335.92		

Chan

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

Admin LG

1/5 19/09/22.

09 Days

total: 11508.26

1/5: 9.2K



AL 8778 1999
24 hr accident call



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: