

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.  
Tel: 6453 8686 (3 Lines) Fax: 6459 6550  
Company Reg. No.: 201113667N  
GST Reg. No.: 201113667N

No. : 06660

Date : 19-Sep-2022

PAGE : 1

NOT Withheld  
1-B-1, 11 Page 8

88505.58

-----

| QTY   | DESCRIPTION                  | UNIT PRICE | TOTAL PRICE | REMARKS |
|-------|------------------------------|------------|-------------|---------|
| 1 pc  | Boot lid                     |            | 826.40      |         |
| 1 pc  | Boot lid rubber              |            |             |         |
| 1 pc  | Boot lid inner lock          |            |             |         |
| 2 pcs | Boot lid hinge               |            |             |         |
| 2 pcs | Boot lid lamp                |            |             |         |
| 2 pcs | Boot lid license plate lamp  |            |             |         |
| 1 pc  | Boot lid no.plate lamp cover |            |             |         |
| 1 pc  | Boot lid inner trim cover    |            |             |         |
| 1 pc  | Boot lid logo                |            |             |         |
| 1 pc  | Boot lid "VIOS" emblem       |            |             |         |
| 1 pc  | Boot lid "G" emblem          |            |             |         |
| 1 pc  | Boot lid press open sensor   |            |             |         |
| 2 pcs | Taillamp                     |            |             |         |
| 2 pcs | Taillamp side clip           |            |             |         |
| 1 pc  | Rear end panel               |            |             |         |
| 1 pc  | End panel top garnish        |            |             |         |
| 2 pcs | Taillamp corner panel        |            |             |         |
| 2 pcs | Rear fender                  |            |             |         |
| 2 pcs | Rear fender inner trim cover |            |             |         |
| 1 pc  | Spare tyre panel             |            |             |         |
| 2 pcs | Spare tyre panel side panel  |            |             |         |
| 1 pc  | Spare tyre board             |            |             |         |
| 2 pcs | Spare tyre board side pad    |            |             |         |
| 1 pc  | Spare tyre nut & screw       |            |             |         |
| 1 pc  | Rear antenel sensor          |            |             |         |
| 1 pc  | Rear bumper fascia           |            |             |         |
| 2 pcs | Rear bumper side retainer    |            |             |         |
| 1 pc  | Rear bumper reinforcement    |            |             |         |

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SMR8386K

Page : 2

|                                |                     |           |    |
|--------------------------------|---------------------|-----------|----|
| 2 pcs Rear bumper reflector    | 015 2.7 @ S\$101.80 | 203.60    | LT |
| 2 pcs Rear bumper side seal    | @ S\$ 78.70         | 157.40    | X  |
| 1 pc Rear exhaust silencer box |                     | 721.40    | X  |
|                                |                     | 12,991.80 |    |
|                                | Less 25% :          | 3,247.95  |    |

1 pc Rear w/s glass sealant  
1 pc Rear no.plate with box  
1 pc Rear bumper clip (set)  
1 pc Rear bumper reverse sensor(set)  
1 pc Rear reverse camera

|                   |        |
|-------------------|--------|
| 9,743.85          |        |
| nn 60.00          | sn X   |
| nn 50.00          | sn 45n |
| nn 30.00          | sn     |
| 200sn CM 300.00   | sn     |
| 160n 200sn 300.00 | sn 2   |

To remove & refix rear windscreen glass and conduct water leak test.

nn 150.00 X

To remove roof lining, front and rear seats, trim board and carpet

120.00 100l

To apply undersealing

100.00 60l

To remove and renew exhaust silencer box

nn 60.00 X

To putty and spray replaced parts

1,300.00 1200l

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

900l  
1,500.00

Total : S\$13,713.85

Singapore Dollars Thirteen Thousand Seven Hundred and Thirteen and Cents Eighty Five Only

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.  
Tel: 6453 8686 (3 Lines) Fax: 6459 6550  
Company Reg. No.: 201113667N  
GST Reg. No.: 201113667N

Vehicle Insured : SMR8386K (INDIA)  
Accident Date : 18-09-2022

Date : 22-09-2022

Our Ref : 022153 / CHAN

YAP WEE HIN  
C/O ALAN'S UNITED AUTO PTE LTD

## SUPPLEMENTARY ITEM PRICE FOR TOYOTA VIOS SMT9885U

1 PC O/S TAILLAMP LOWER BRACKET

|          |                |   |
|----------|----------------|---|
| CM       | \$65.00        | ✓ |
| LESS 25% | \$16.25        |   |
|          | <u>\$48.75</u> |   |

Singapore Dollars Forty Eight And Cents Seventy Five Only