

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 21 Sep 2022

Preliminary Advice

Vehicle No	: SKD8658Z	Accident Date	: 10/09/2022
Make	: HONDA CROSSROAD	Policy No.	: MPC21P00262200
Assignment Date	: 19/09/2022	Excess	: S\$0.00
Date of Inspection	: 20/9/2022	Est. Duration of Repair	: 8
Inspection At	: ZHONG CHENG ENTERPRISE		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,972.03
Revised Amount	:S\$	11,020.50
Check Items (Estimated)	:S\$	308.00
Total	:S\$	11,328.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	11,000.00
COE / PARF Rebate	:S\$	2,684.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,300.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .