ASS. REC. BY:	20072201Kg
Kenneth ASS	SIGNMENT
From: Date:	Veh No: SIN 8385X Yr Regn: 05, 17
Estimated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD AP I WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toy Privs c.c 1797
at Workshop m/s Note work	Colour A. Pilm A/C: Insured / Std / NI / NA
603G	Sp.Reading 392773 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No;
Policy No.	CNO: ZVW50 . 6050507
Claims No.	Gen. Cond: Good'/ Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder's Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nii / S/Rim / STD A/Rim or
( · )	Tyre Size: F: 195/65R 15
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/SU	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Go form
Bal. or Market Value: 8736	Email
IDAC Accident Rport: Consistent? : Yes or No	R/Bal 9
GIA / PR Seen: Consistent?: Yes or No	Mm 100d. / mm
Set Bearing	/ mm
Lum Sum: 22 ov 3 Vol. Von and	Consultation
	Survey held at 11.33
. Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Person Contacted:	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
- Got BI, GIA not ready	
2	
	· · · · · · · · · · · · · · · · · · ·
1	
Date/Time, File Pass to? Prell. Report Day	s Of Repair:
Ciuta/Time, File Return to?	
Add Fee:	Transportativi:
Add Fee:	: Site Insp (\$)s -RSSI
	: Interview (\$ ), Fire is
Report Format :	Tech Invs (\$ ), Others
.ump Sum / I.B.I: (S	
	Weekend (\$
	ICTAL

# **AUTOWORX HOUSE**

176 SIN MING DRIVE #02-01 SINGAPORE 575721 TEL: 64528211 FAX: 64517420

# **ESTIMATE**

NOT NOT has no 11 hay 8 Accord After Paint 5 days

**MCQUEEN RENTALS PTE LTD** 

c/o 46 Lentor Plain Singapore 786548

Date:

20/9/2022

		AMOUNT (\$)	
QUANTITY	PARTICULARS	7 1111 0 1 1 1 1 1	
1 pc 1 pc 1 pc 1 pc 8 pc 1pc 1 pc 1 pc	PARTICULARS  RE: TOYOTA PRIUS HYBRID / SLN 8385 X  Front fender Front fender emblem "HYBRID" Front fender dust cover Front fender dust cover clip Front bumper Front bumper Front bumper side retainer Front head lamp	R <sub>1</sub> 766.50 N <sub>2</sub> 76.80 CM 264.30 N <sub>2</sub> 28.80 (CM 967.80 P1776.40 G1 2,165.40	
1 pc 1 pc 1 pc 1 pc 1 pc 1 pc 1 pc	Alloy rim Front knockle arm Front wheel bearing Front shock absorber Front lower arm Front steering tie rod Front steering tie rod end	690.00 565.40 316.50 567.10 367.30 116.50	7777
	sub-totaless 20 sub-totaless 2	%2 <u>56</u> 1,426.31	0

balance brought forward.

To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.

To check wiring system.

To apply putty & spray painting on affected areas.

To change the alloy rim.

To checke the wheel alignment.

To change the front RH under carriage

total

5,705.20

4001 1,000.00

201 60.00

400 800.00

201 40.00

601 85.00

250.00

7,940.20

# LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before after spray painting
   To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





Police Station Of Origin: Ang Mo Kio South N.P.C 81 Ang Mo Kio Avenue 3 SINGAPORE 569929

Report No. T/20220917/2068

1 of 3

Tel No: 1800-4519999

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/09/2022 18:45		Made:	Vide Report No.: E/20220917/0098	Station Diary No.: 96
Informar	nt's Partici	ulars		<b>科技的</b> 。
	Informant: T SUEN, E	UGENIUS	Address: APT BLK 68 GEYLANG BAHF 330068	RU #10-3225 SINGAPORE
ID Type / ID No.: NRIC NO / S9703685C		35C	Contact No.: Home/Office:	Mobile: 83837413
Nationality SINGAPO		ΞN	Email:	
Sex: Male	Age: 25	Date of Birth: 03/02/1997	Type of Informant: Driver	
Race: Chinese		a a	Language: English	Institution / School Name:
Occupation:		IVER	Driving Licence Information:	Date of Expiry:

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/09/2022 12:00	Type of Location:
Location: WHITLEY ROAD		*		
Weather: Raining		Road Surface: Wet	F	Road Speed Limit:
Traffic Flow:	,	Traffic Control:		Traffic Volume:
ype of Collision:			;	Anyone conveyed by ambulance: Yes

The second secon	ehicle Involve	THE CHIEF PROPERTY PROPERTY AND ADDRESS OF THE PARTY.			A	No of Doggooga
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenge
FBR2989R	Motorcycle					0
SLN8385X	Car					2

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





Police Station Of Origin: Ang Mo Kio South N.P.C 81 Ang Mo Kio Avenue 3 SINGAPORE 569929

Tel No: 1800-4519999

2 of 3 Report No. T/20220917/2068

#### **CONTINUATION OF REPORT**

Rider				N. 1 4 11 10		
Name	DHRUVAL		ID No.	*	NIL .	
Related Vehicle	FBR2989R (Motorcycle)		Contact No.		85403417	
Hospital/Clinic	NIL .			Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discl	narge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	Injury	NIL	
Driver						
Name	TENG YIT SUEN, E	UGENIUS		ID No	•	S9703685C
Related Vehicle	SLN8385X (Car)		1	Conta	ct No.	83837413
Hospital/Clinic	MOUNT ALVERNIA	HOSPITAL	·	Class Drivin Licen	g	Class: 3 Date of Expiry: NIL
				Expir	y Date	
ate Treatment	17/09/2022		Date Disc			9/2022
	ed Medical Leave	05	Degree of	f Injury	NIL	

### **Brief Details.**

On the 17/09/2022 at about 1200hrs, I was driving my GoJek car SLN8385X at along Whitley Road towards Malcom Road. I just drove in from PIE. I had 2 passengers in my car at the rear. I was driving at the most right lane. The weather was raining and wet. As I passing by the Caltex Station, suddenly a motor cyclist FBR2989R rode out from the Caltex station on my right side. Upon seeing him, I immediately swerved to my left side to avoid accident, however the bike still collided with my car's right side bumper area near above the front right tire. The rider then fell down and was seen injured. I then called the 999 for assistant.

Shortly, Police and Ambulance came to scene and assisted. The Police had seized my car camera's SD card for investigation. The rider was conveyed to hospital. Later the day, I started to feel pain on my neck. Thus I went to Mount Alvernia Hospital to consult doctor and I was given 5 days of MC. Due to the accident, my car's front right side bumper area near the front tire was dented and damaged.