

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009237/EVY3Q2**Date:** 24/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00203432100

Claimant Vehicle No : SLQ8188H **Insured Vehicle No :** SMF1979J

Date of Loss: 16/09/2022 Nature of Claim: TP Claim No: SNM22D206659/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ8188H**

Make & Model: NISSAN SERENA, 1.2 Highway Star Premium E-Power (A) Engine No: HR12223497K

Reg. Date: 10/06/2021 (Man. Year: 2020) Chassis No: JN1EBAC27Z0001039

Colour: White Odometer: 16285 km

Engine Capacity: 1198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R16 Rear Tyre Size: 225/50 R16

Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	62.88	42.88	20.00	31.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	780.00	320.00	29.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,162.88	822.88	340.00	29.24
+ GST 7.00/7.00% (S\$)	81.40	57.60	23.80	29.24
Nett Amount (S\$)	1,244.28	880.48	363.80	29.24

INSPECTION

Date of Assignment: 20/09/2022

Date Inspected: 21/09/2022 Inspected At: Tan Chong Motor Sales Pte Ltd (HQ)
911 BUKIT TIMAH ROAD
Singapore 589623

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:		MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2022)
Parts:	M1-MPV	NISSAN SERENA 1.2 Highway Star Premium E-Power (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLQ8188H)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Not Necessary	20.00 FS	*- FS
2	4		*END RUB (GREY) BUMPER SPOILER	Necessary	53.60 FN	*53.60 FN
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (S\$)					73.60	53.60
- Nett Item Discount on N Items 20.00/20.00% (S\$)					10.72	10.72
Total Parts (S\$)					62.88	42.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR FRONT BUMPER AND BUMPER SPOILER	New	500.00	280.00
2	S/PAINT FRONT BUMPER AND BUMPER SPOILER	New	600.00	500.00
Gross Labour Cost (\$)			1,100.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >