

ASS. REC. BY:

Steve

CS/CTI 12 009237/ERY3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLQ 8788H Yr Regn: 10/6/21Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Nissan Serena c.c. 1798Colour: White A/C: Insured / Std / NI / NASp. Reading: 16285 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNIEBAC772001039

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MY / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 16/9/21 D.O.I. 21/9/21Survey held at Tan chong

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-175K

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.F. (%)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0273/2022
DATE : 19-SEP-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : MR CHIU YEW CHAI
ADDRESS : BLK 6 BUKIT BATOK STREET 41
#09-15
S(657992)
TELEPHONE NO : 86138188/81386342

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SMF1979J
VEHICLE NO : SLQ8188H
MODEL CODE : EDWARW9C27HWA-----
MODEL/YEAR : NISSAN SERENA E-POWER 1.2 HIGHWAY STAR MY2019
ENGINE NO : HR12223497K
CHASSIS NO : JN1EBAC27Z0001039
MILEAGE : 1 KM
DATE IN : 19/09/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 16/09/2022

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR IN WORKSHOP / CAR NOT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H / P : 94568832 FAX : 64697472

Licki
WATSON
21/09/2022
3pm

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLQ8188H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPAIR FRONT BUMPER AND BUMPER SPOILER	500.00	280
2	ZZ/002	S/PAINT FRONT BUMPER AND BUMPER SPOILER	600.00	500
TOTAL LABOUR CHARGES			1100.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLQ8188H

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NPN			20.00 ?
2 END RUB (GREY) BUMPER SPOILER \$13.40 EA X 04	76859-9A75A	53.60	AK	
SUB TOTAL		53.60	0.00	20.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		10.72	0.00	0.00
GRAND TOTAL		42.88	0.00	20.00
OVERALL TOTAL		62.88		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLQ8188H

TOTAL LABOUR CHARGES	1100.00
TOTAL SPARE PARTS CHARGES	62.88
GRAND TOTAL	1162.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

Steve (LKK)
21/9/22, 3:00pm

m n
P/P
hy BL sy
3 dpr

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: