

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22009239/UPA3Q2**Date:** 20/07/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SPMF1000000538

Claimant Vehicle No : FBU1688A **Insured Vehicle No :** GBF4162J

Date of Loss: 13/09/2022 Nature of Claim: TP Claim No: SVRAISCL2022-00053

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBU1688A**
 Make & Model: BMW R1200GS, 1.2 (M) Engine No: 122EN35150905
 Reg. Date: 04/08/2016 (Man. Year: 2016) Chassis No: WB10A0205GZ227830
 Colour: Red Odometer: 33549 km
 Engine Capacity: 1170 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70 R19 Rear Tyre Size: 170/60 R17
 Front Left Side: Metzeler 8 mm Rear Left Side: Metzeler 8 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,630.00	6,238.80	11,391.20	64.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	620.00	400.00	220.00	35.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,250.00	6,638.80	11,611.20	63.62
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	18,250.00	5,300.00	12,950.00	70.96
+ Loss of Use (5.0 x S\$30.00/day) (S\$)		150.00		
Nett Liability (S\$)		5,450.00		

INSPECTION

Date of Assignment: 20/09/2022

Date Inspected: 21/09/2022 Inspected At:

 Erofia Motor Trading Pte Ltd (KAKI BUKIT)
 1 KAKI BUKIT AVE 6 #02-62
 Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Jul 2023)	
Parts:	N/A	BMW R1200GS 1.2 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBU1688A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Not Necessary	1,580.00 FL	*- FL
2	1		*SIDE MIRROR -R/H	Not Necessary	920.00 FL	*- FL
3	1		*REAR CRASH BAR	Bent	2,650.00 F	*1,500.00 FN
4	1		*SET FRONT CRASH BAR	Bent / Cut	3,100.00 F	*1,300.00 FN
5	1		*FRONT CRASH SIDE PROTECTOR -L/H	Serviceable	450.00 F	*- FN
6	1		*HANDLE BAR PROTECTOR (N/S)	Cut	960.00 F	*302.00 FN
7	1		*SET CAMERA	Not Necessary	600.00 F	*- FN
8	1		*SET SPOT LIGHT (UPPER) (O/S CUT)	Not Consistent With The Impact	880.00 F	*- FN
9	1		*SET SPORT LIGHT (LOWER) (O/S Scratched)	Not Consistent With The Impact	620.00 F	*- FN
10	1		*REAR BOX	Dented	2,860.00 F	*1,600.00 FN
11	1		*REAR BOX BRACKET	Bent	780.00 F	*480.00 FN
12	1		*REAR SIDE BOX -L/H	Damaged / Cut	2,480.00 F	*1,750.00 FN
						F=Franchise part. L=ListItemDisc. N=NettItemDisc.
					Sub Total (\$\$)	17,880.00 6,932.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	250.00 0.00
					- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00 693.20
					Total Parts (\$\$)	17,630.00 6,238.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE LABOUR	New	620.00	400.00
Gross Labour Cost (\$\$)			620.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >