



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22009242/Any3q2	
			Date: 17/10/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 9462R		Veh. Inspected	SLV 8832E
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2203346/GPL		Excess (\$)	0.00
Assign From	GRACE TEO		Assign Date	20/09/2022
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 520D		c.c	1995
Engine No.	HIDDEN		Year of Reg.	2017
Chassis No.	WBAJC32080G580953		Colour	SILVER
Odometer	159523 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		245/40 R19	GOODYEAR	6 mm
L/H Front Tyre		245/40 R19	GOODYEAR	6 mm
R/H Rear Tyre		245/40 R19	GOODYEAR	6 mm
L/H Rear Tyre		245/40 R19	GOODYEAR	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/09/2022		Inspection Date	20/09/2022
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	