

YSK AUTO WORKSHOP

1 Kaki Bukit Avenue 6, Blk D #01-71

Registration No. / Unique Entity Number: 53311047E

Estimate for SLV8832E(BMW 520D)

T P Sompoo
Hui Ray

WBAJC32080G580853.

- 1 *LH TENSION STRUT WITH HYDR MOUNT *new*
- 1 *WISHBONE TOP *new*
- 1 *LH WISHBONE BOTTOM RUBBER MOUNT *new*
- 1 *WHEEL HUB WITH BEARING FRT *new*
- 1 *FRT LH SPRING STRUT *new*
- 1 *FRONT SWING SUPPORT *new*
- 1 *STABILIZER FRT WITH RUBBER MOUNTING *new*
- 1 *LH TIE ROD *new*
- 1 *ALLOY RIM 91/2JX19 STY SPOKE 272 *new*
- 1 *FRT LH FENDER *Disturbed.*
- 1 *FRT LH FENDER SHIELD *torn*
- 1 *FRT BUMPER CARRIER *new*
- 1 *IMPACT ABSORBER TOP *new*
- 1 *FRT BUMPER (PDC) *Disturbed.*
- 1 *COVERING PRIMED LH *new*
- 1 *COVERING PRIMED RH *new*
- 1 *BMW EMBLEM *new*
- 1 *AHL XENON HEADLIGHT LH LED MODULE *new*
- 1 *AHL XENON HEADLIGHT LH *can be used*
- 6 *DECOUPLING RING PDC TORQUE CONVERTER *new*
- 6 *BUMPER PDC SENSOR (A90 SOPHISTOGRAU) *2 pieces damaged*
- 1 *FRT BUMPER LH SPACER *new*
- 1 *FRT BUMPER RH SPACER *new*

Less 5%

- *FRONT BUMPER CLIPS *new*
- *FRONT LH SPLASH SHIELD CLIPS *new*
- *FRONT LH TYRE *new*

- REPLACE AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT
- SPRAY PAINTING DAMAGED PORTION
- TO TOW ACCIDENT VEHICLE TO WORKSHOP
- TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT
- TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING LEFT FRONT

To perform diagnostic test

	\$492.90	x
	\$542.20	x
	\$591.50	x
	\$1,006.00	577.
	\$600.85	298
	\$221.20	x
	\$469.25	x
	\$352.90	x
1200	\$1,508.60	850(SN).
	\$884.85	x
	\$325.20	x
	\$698.50	x
	\$45.60	x
	\$1,403.10	x
	\$86.45	x
	\$86.45	x
	\$69.50	x
	\$285.10	x
	\$4,960.90	x
	\$120.20	x
	\$1,475.20	490
	\$88.65	x
	\$88.65	x
	\$16,403.75	
	\$820.19	
	\$15,583.56	

\$80.00	30
\$80.00	30
\$800.00	x
\$960.00	

\$1,000.00	500
\$1,000.00	500
\$150.00	80
\$150.00	80
\$50.00	
200.	120.

953860
Len 5% 906167.
S.N: 1200

60

TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR
PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS

~~\$120.00~~ 50

TO CARRY OUT BODY CAVITY PRESERVATION

~~\$120.00~~ 50

TO REMOVE AND INSTALL FRONT SUSPENSION FOR INSPECTION AND
REPLACE DAMAGED PARTS

~~\$250.00~~ 150

\$2,840.00

Total

\$19,383.56

Adrian Ly
L/c 20/09/22
OSHP.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 11901.67

L/s: 9.51C

9.51C