## MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

Quotation

Tel: 67484422 / 67454422 Fax: 6747- 6720 REG NO 200501102H

ALLIANZ INSURANCE SINGAPORE PTE LTD

DATE : 04.10.2022

VEH NO : SJX2888Y

79 Robinson Road #09-01
Singapore 068897

X100 Tory
MODEL : BMW 1181
D O A : 13.09.2022

V YR REF : SKV5351H

Attn: Motor Claim Dept (Pls arrange vehicle survey & check liability)

## RE: ESTIMATE FOR ACCIDENT REPAIR SJX2888Y (BMW 118i)

RE:	ESTIMATE FOR ACCIDENT REPAIR S	SJX2888Y (BMW	1101)		
Item	Description		Qty	Amt	
1 2 4 3 4 5 6	Rear Bumper Delad Rear Bumper Side Holder - LH & RH Rear Bumper Outer Chrome Moulding Rear Bumper Reflector - LH & RH Rear Bumper Reinforcement Reverse Sensor Reverse Sensor Daylor Reverse Sensor Holder	yn	1	312.50	1,020.00 513 100.00 513 3,996.60 (399.66)
1	S/NETT ITEMS  Rear Bumper Clips  M	Total Parts	1 set	<i>\$0</i>	3,596.94 50.00 3,646.94
1	LABOUR CHARGE  To knocking & pull out rear portion & renew parts			\$	400.80 253- 400.80 257 50.00 30
2	To putty & spray up paint works		550	\$	400,00 230
3	To check wiring			\$	50.00 30
4	To remove reverse sensor	Total Labour		\$	950.00
		Grand Total		\$	4,596.94

## RE: ESTIMATE FOR ACCIDENT REPAIR SJX2888Y (BMW 118i)

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

tolal 2721 25 (CP/P) 03 Days

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: