

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 19.09.2022

TO : EQ MOTOR CLAIMS DEPTS
VEHICLE NO : SLR756R
MODEL : TOYOTA VIOS
DATE OF ACCIDENT : 19.09.2022
TIME OF ACCIDENT : 12:30 HRS

Xiao Chen.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Buckled</i>	1	\$ 575.00	\$ 575.00
2	BOOT LID LOGO <i>2</i>	1	\$ 70.00	\$ 70.00
3	BOOT LID EMBLEM 'VIOS' <i>1</i>	1	\$ 65.00	\$ 65.00
4	BOOT LID EMBLEM 'E' <i>1</i>	1	\$ 55.00	\$ 55.00
5	BOOT LID TOP LOCK <i>2nd</i>	1	\$ 155.00	\$ 155.00
6	BOOT LID LOWER LOCK <i>me in</i>	1	\$ 25.00	\$ 25.00
7	BOOT LID WEATHER STRIP <i>lit</i>	1	\$ 205.00	\$ 205.00
8	BOOT LID HINGE <i>Not in</i>	2	\$ 70.00	\$ 140.00
9	REAR BUMPER <i>Dehnd</i>	1	\$ 495.00	\$ 495.00
10	REAR BUMPER REFLECTOR <i>LH could</i>	2	\$ 105.00	\$ 210.00
11	REAR BUMPER BRACKET <i>LH Best</i>	2	\$ 89.00	\$ 178.00
12	REAR BUMPER SIDE RETAINER (FRONT) <i>2 LH</i>	2	\$ 105.00	\$ 210.00
13	REAR BUMPER SIDE RETAINER (REAR) <i>2nd</i>	2	\$ 55.00	\$ 110.00
14	TAIL LAMP <i>LH could</i>	2	\$ 345.00	\$ 690.00
15	REAR FENDER INNER COWLING <i>me in</i>	2	\$ 175.00	\$ 350.00
16	REAR FENDER INNER TRIM <i>Not in</i>	2	\$ 295.00	\$ 590.00
17	REAR CHASSIS MEMBER LH <i>ME in</i>	1	\$ 694.30	\$ 694.30
18	REAR END PANEL <i>Dehnd</i>	1	\$ 439.00	\$ 439.00
19	REAR FLOOR PANEL <i>Regis</i>	1	\$ 890.00	\$ 890.00
20	REAR END PANEL TOP GARNISH <i>Dehnd</i>	1	\$ 230.00	\$ 230.00
21	REAR FLOOR PANEL TOP BOARD <i>torn</i>	1	\$ 175.00	\$ 175.00
22	REAR FLOOR PANEL TOP SPONGE (SIDE) <i>Dehnd</i>	2	\$ 275.00	\$ 550.00

3438
2578-50

TOTAL PRICE \$ 7,101.30
LESS 25% \$ 1,775.33
SUB TOTAL PRICE \$ 5,325.98

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

TO : EQ MOTOR CLAIMS DEPTS
 VEHICLE NO : SLR756R
 MODEL : TOYOTA VIOS
 DATE OF ACCIDENT : 19.09.2022
 TIME OF ACCIDENT : 12:30 HRS

1	REAR NUMBER PLATE <i>Not in</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
3	BOOT LID OUTER MOULDING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
4	BOOT LID EMBLEM 'SPORT' <i>new</i>	1	\$ 80.00	\$ 80.00	60
5	REAR SPOILER <i>Behind new</i>	1	\$ 850.00	\$ 850.00	500 +
6	REAR FENDER INNER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
8	TAIL LAMP CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	10
9	REAR LOWER LID (SPECAIL TYPE) <i>Behind</i>	1	\$ 1,000.00	\$ 1,000.00	600
10	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	10
11	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
12	REAR EXHAUST CHROME PIPE (SPECIAL TYPE) <i>new</i>	1	\$ 250.00	\$ 250.00	+
13	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	+
14	REVERSE SENSOR <i>Behind</i>	1	\$ 220.00	\$ 220.00	200

970

TOTAL \$ 3,350.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, KNOCK, GRAZE, ADJUST, REPLACE NEW PARTS	\$ 2,200.00	800
2	TO PUTTY, SPRAY PAINT, POLISH, WAX ADJACENT PANELS	\$ 1,400.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING/ BULB CHECKING	\$ 80.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 200.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	X
8	TRANSFER BOOT LID MECHANISM	\$ 80.00	60
9	REMOVE AND REFIX REAR SPOILER AND DIFFUSER	\$ 300.00	X
10	TO CONDUCT WATER LEAKAGE TEST	\$ 80.00	X

TO : EQ MOTOR CLAIMS DEPTS
VEHICLE NO : SLR756R
MODEL : TOYOTA VIOS
DATE OF ACCIDENT : 19.09.2022
TIME OF ACCIDENT : 12:30 HRS

11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	---	-----------	---

TOTAL \$ 4,930.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,675.98
TOTAL LABOUR COST : \$ 4,930.00
TOTAL REPAIR COST : \$ 13,605.98

1860 Admin Lj
H/s 29/09/22
06 Pyp.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

total: 5408.50
L/s: 4.3K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: