

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: HL Assurance Pte Ltd
11 Keppel Road
#11-01 ABI Plaza
Singapore 089057From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: ALANO Ana Maria Velarde

Date: 22 Sep 2022

Preliminary Advice

Vehicle No	: SLA1311Z	Accident Date	: 19/09/2022
Make	: BMW 216I	Policy No.	: MP319661
Assignment Date	: 20/09/2022	Excess	: S\$0.00
Date of Inspection	: 21/09/2022	Est. Duration of Repair	: 10
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,603.40
Revised Amount	:S\$	20,496.05
Check Items (Estimated)	:S\$	4,953.35
Total	:S\$	25,449.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	143,000.00
COE / PARF Rebate	:S\$	60,857.00
Salvage Value	:S\$	
Margin for Repair	:S\$	82,143.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.