



AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@KB Singapore 415875

Tel: 6789 5155 Fax: 6783 5155

Co. Reg No.: 201500047H GST No.: 201500047H

Email: wendy@autobacs.com.sg

TO	: NTUC (SLH1771S)	DATE	: 19-09-2022
ATTENTION	: Motor Claims Department	JOB TYPE	: T/P Claims
VEHICLE DETAILS		ACCIDENT DETAIL	
VEHICLE NO.	: SGD5668L	DATE	: 14-09-2022
MAKE / MODEL	: TOYOTA AXIO	TIME	: 1830HRS
CHASSIS NO.	: NRE161-0003112	Veron	

CLAIM DETAIL : PARTS PRICE (\$\$)

S/N	DESCRIPTION	QTY	UNIT LIST	TOTAL LIST
1	FRONT BUMPER	1	\$ 494.23	\$ 494.23
2	FRONT BUMPER BRACKET RH	1	\$ 54.20	\$ 54.20
3	FRONT HEADLAMP RH	1	\$ 648.20	\$ 648.20
4	FRONT HEADLAMP BRACKET RH	1	\$ 63.80	\$ 63.80
5	FRONT FENDER RH	1	\$ 452.90	\$ 452.90
6	FRONT DOOR RH <i>Derided</i>	1	\$ 1,185.39	\$ 1,185.39
7	FRONT DOOR HANDLE RH <i>He m</i>	1	\$ 362.09	\$ 362.09
8	FRONT DOOR LOCK RH <i>He m</i>	1	\$ 470.36	\$ 470.36
9	FRONT DOOR HINGE RH TOP <i>3 m</i>	1	\$ 82.59	\$ 82.59
10	FRONT DOOR HINGE RH BOTTOM <i>3 m</i>	1	\$ 83.31	\$ 83.31
11	FRONT DOOR WEATHER STRIP <i>He m</i>	1	\$ 230.80	\$ 230.80
12	FRONT DOOR WINDOW FRAME GARNISH RH <i>3 m</i>	1	\$ 70.20	\$ 70.20
13	FRONT DOOR WINDOW FRAME GARNISH LH <i>3 m</i>	1	\$ 86.50	\$ 86.50
14	FRONT DOOR INNER SPONGE <i>3 m</i>	1	\$ 78.90	\$ 78.90
15	FRONT DOOR CHROME MOULDING <i>3 m</i>	1	\$ 265.90	\$ 265.90
16	FRONT DOOR REGULATOR MOTOR RH <i>3 m</i>	1	\$ 721.60	\$ 721.60
17	FRONT DOOR REGULATOR CHANNEL RH <i>3 m</i>	1	\$ 95.20	\$ 95.20
18	REAR DOOR RH <i>Derided</i>	1	\$ 1,176.83	\$ 1,176.83
19	REAR DOOR HANDLE RH <i>He m</i>	1	\$ 94.65	\$ 94.65
20	REAR DOOR LOCK RH <i>He m</i>	1	\$ 520.50	\$ 520.50
21	REAR DOOR HINGE RH <i>3 m</i>	2	\$ 88.60	\$ 177.20
22	REAR DOOR HINGE RH BOTTOM	1	\$ 83.31	\$ 83.31
23	REAR DOOR WEATHER STRIP <i>He m</i>	1	\$ 230.80	\$ 230.80
24	REAR DOOR WINDOW FRAME GARNISH RH <i>3 m</i>	1	\$ 70.20	\$ 70.20
25	REAR DOOR WINDOW FRAME GARNISH LH	1	\$ 86.50	\$ 86.50
26	REAR DOOR INNER SPONGE <i>He m</i>	1	\$ 78.90	\$ 78.90
27	REAR DOOR CHROME MOULDING <i>He m</i>	1	\$ 210.80	\$ 210.80

28	REAR DOOR BOARD <i>Abel m</i>	1	\$	1,053.90	\$	1,053.90	<i>+</i>
29	REAR DOOR REGULATOR MOTOR RH <i>Abel m</i>	1	\$	660.28	\$	660.28	<i>+</i>
30	REAR DOOR REGULATOR CHANNEL RH <i>Abel m</i>	1	\$	96.80	\$	96.80	<i>+</i>
31	REAR FENDER RH <i>Regis</i>	1	\$	1,291.88	\$	1,291.88	<i>+</i>
32	REAR FENDER INNER SHIELD RH <i>Abel m</i>	1	\$	237.80	\$	237.80	<i>+</i>
33	REAR BUMPER <i>Abel m</i>	1	\$	516.23	\$	516.23	<i>+</i>
34	ROCKER PANEL RH <i>Regis</i>	1	\$	148.59	\$	148.59	<i>+</i>
35	REAR DOOR STOPPER <i>Abel m</i>	2	\$	195.20	\$	390.40	<i>+</i>

Total : \$ 12,571.74

-25% \$ 3,142.94

SUB TOTAL : \$ 9,428.81

2 362.22

1771.66

CLAIM DETAIL : PARTS S/NETT

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIPS SET <i>Abel m</i>	SET	\$ 80.00	\$ 80.00	<i>+</i>
2	FRONT FENDER SEALANT <i>Abel m</i>	1	\$ 100.00	\$ 100.00	<i>+</i>
3	FRONT FENDER INNER SEALANT <i>Abel m</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
4	REAR BUMPER CLIPS SET <i>Abel m</i>	SET	\$ 80.00	\$ 80.00	<i>+</i>
5	FRONT DOOR BOARD CLIPS SET RH <i>Regis</i>	SET	\$ 60.00	\$ 60.00	<i>+</i>
6	REAR DOOR BOARD CLIPS SET LH <i>Regis</i>	SET	\$ 60.00	\$ 60.00	<i>+</i>
7	ROCKER PANEL SEALANT RH <i>Abel m</i>	1	\$ 80.00	\$ 80.00	<i>+</i>

S/NETT TOTAL : \$ 520.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,800.00	500
TO SPRAY PAINTING ALL THE ACCIDENT PORION & POLISHING AFFECTED AREA	\$ 1,800.00	800
TO APPLY ANTI-RUST & TUFF KOTE	\$ 150.00	60
TO PERFORM LIGHTING & WIRING CHECK	\$ 150.00	30
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 100.00	X
TO DISMANTLE & REINSTALL INTERIOR FRONT AND REAR DOOR INNER COMPONENT MECHANISM RH YO FACILITATE REPAIR WITH CHECKING	\$ 300.00	160
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SONSOR WITH DISTANCE SETTING	\$ 250.00	X.

1580

LABOUR TOTAL : \$ 4,550.00**ESTIMATE REPORT**

TOTAL PARTS : \$ 9,948.81
TOTAL LABOUR : \$ 4,550.00
TOTAL AMOUNT : \$ 14,498.81

Adrian G

h/e 20/09/22

04 Days

Total: 3351.66

h/s: 2650.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: