

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 19.09.2022

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **GBH8192K**
MODEL : **TOYOTA PROACE**
DATE OF ACCIDENT : 16.09.2022
TIME OF ACCIDENT : 18:00HRS

YA RVBBHVB62104428
Hui Rong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR LH <i>Dented</i>	1	\$ 1,899.00	\$ 1,899.00
2	FRONT DOOR OUTER STRIP LH <i>new</i>	1	\$ 107.30	\$ 107.30
3	FRONT DOOR HINGE LH <i>new</i>	2	\$ 73.20	\$ 146.40
4	FRONT DOOR INNER LOCK LH <i>new</i>	1	\$ 534.70	\$ 534.70
5	FRONT DOOR INNER TRIM LH <i>new</i>	1	\$ 890.20	\$ 890.20
6	FRONT DOOR LOCK CATCHER LH <i>new</i>	1	\$ 30.40	\$ 30.40
7	FRONT DOOR WEATHER STRIP LH <i>new</i>	1	\$ 171.20	\$ 171.20
8	FRONT DOOR POWER WINDOW MOTOR LH <i>new</i>	1	\$ 679.80	\$ 679.80
9	FRONT DOOR PILLAR LH <i>new</i>	1	\$ 1,352.90	\$ 1,352.90
10	FRONT FENDER LH <i>Dented</i>	1	\$ 747.10	\$ 747.10
11	FRONT FENDER INNER GARNISH LH <i>new</i>	1	\$ 108.00	\$ 108.00
12	FRONT FENDER SUPPORT BRACKET LH <i>new</i>	1	\$ 59.80	\$ 59.80
13	FRONT FENDER LAMP LH <i>new</i>	1	\$ 42.30	\$ 42.30
14	FRONT FENDER UPPER CORNER GARNISH LH <i>new</i>	1	\$ 58.40	\$ 58.40
15	FRONT FENDER INNER COWLING LH <i>new</i>	1	\$ 179.80	\$ 179.80
16	SIDE MIRROR <i>new</i>	1	\$ 1,276.90	\$ 1,276.90

3965.30
2973.97

TOTAL PRICE \$ 8,284.20
LESS 10% \$ 828.42
SUB TOTAL PRICE \$ 7,455.78

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR SEALANT LH <i>new</i>	1	\$ 150.00	\$ 150.00
2	FRONT DOOR INNER TRIM CLIP LH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
3	FRONT DOOR LTA SETICKER (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
4	FRONT FENDER INNER COWLING CLIP LH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00

TOTAL \$ 250.00

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **GBH8192K**
 MODEL : **TOYOTA PROACE**
 DATE OF ACCIDENT : 16.09.2022
 TIME OF ACCIDENT : 18.00HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	500
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	500
3	TUFF COAT	\$ 250.00	50
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	x
6	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	x
7	TRANSFER FRONT DOOR MECHANISM LH	\$ 80.00	40
8	REMOVE & REINSTALL FRONT WINDOW GLASS LH	\$ 80.00	40
9	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 3,660.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,705.78
 TOTAL LABOUR COST : \$ 3,660.00
 TOTAL REPAIR COST : \$ 11,365.78

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
 r/s 20/09/22
 05 Days

total: 4173.97

2/8: 3.3K

3.314