

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21007715/GQY3E2-1**Date:** 28/11/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001484645

Claimant Vehicle No : FBS6585R**Insured Vehicle No :** SMS5987R

Date of Loss: 09/07/2021

Nature of Claim: TP

Claim No: 259884

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBS6585R**

Make & Model: HONDA CBR150R, 150cc

Engine No: KC92E1024507

Reg. Date: 29/06/2021 (Man. Year: 2019)

Chassis No: MH1KC9217KK026803

Colour: Black

Odometer: 438 km

Engine Capacity: 149 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80-17

Rear Tyre Size: 130/70-17

Front Left Side: IRC 6 mm

Rear Left Side: IRC 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,599.60	854.10	745.50	46.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	230.00	230.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,829.60	1,084.10	745.50	40.75
+ GST 7.00/7.00% (S\$)	128.07	75.89	52.18	40.74
Nett Amount (S\$)	1,957.67	1,159.99	797.68	40.75

INSPECTION

Date of Assignment: 16/07/2021

Date Inspected: 11/10/2022 Inspected At:

Everbright Motor Cycles Co (HQ)
 53 Paya Ubi Industrial Park, #01-10/12 Ubi Avenue
 1
 Singapore 408934

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Nov 2022)	
Parts:	N/A	HONDA CBR150R 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBS6585R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CLUTCH LVER	Replaced	26.40 F	*19.00 FL
2	1		*BRAKE LEVER	Serviceable	33.60 F	*- FL
3	1		*LEFT MIRROR	Replaced	81.60 F	*55.00 FL
4	1		*RIGHT MIRROR	Serviceable	81.60 F	*- FL
5	1		*HANDLE BALANCING BAR ONE SET	Replaced	43.20 F	*22.00 FL
6	1		*RIGHT FRONT FAIRING	Replaced	252.00 F	*185.00 FL
7	1		*HEAD LAMP	Replaced	624.00 F	*435.00 FL
8	1		*LEFT & RIGHT SIGN LIGHT	N/S Replaced / O/S Serviceable	115.20 F	*48.00 FL
9	1		*CENTRE FAIRING	Replaced	342.00 F	*185.00 FL
					Sub Total (\$\$)	1,599.60 949.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 94.90
					Total Parts (\$\$)	1,599.60 854.10

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE	New	230.00	230.00
Gross Labour Cost (\$\$)			230.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >