

ASS. REC BY: Taughn

REF:

LPL

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated cost: \_\_\_\_\_

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value: \$85K.

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

WP

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GRK 9364J Yr Regn: 2021 / Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.O. 2982Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 43593 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTFHT02P500\*251169.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/15R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mmR/Bal. 6 mmL/Bal. 6 mmD.O.A. 20/9/22Survey held at EM-1 Auto.Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

|  |  |
|--|--|
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |
|  |  |

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: \_\_\_\_\_

Lump Sum / I.B.L. (%) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GBK 9634J

Date : 20.09.2022

Vehicle Model : TOYOTA HIACE

Chassis : JTFHT02P500251169

Accident Date : 19.08.2022

TP Ins. **LONPAC**

Original Reg Date : 15.01.2021

## ESTIMATE

|          |      |                         |       |     |          |
|----------|------|-------------------------|-------|-----|----------|
| 1        | 1 pc | Sliding Door RH         |       | Rp  | 1,718.80 |
| 2        | 1 pc | Sliding Door Railing RH | photo | cut | 292.00   |
| 3        | 1 pc | Rear Side Panel RH      |       | btt | 1,986.50 |
|          |      |                         |       |     | 3,997.30 |
| Less 25% |      |                         |       |     | 999.33   |
|          |      |                         |       |     | 2,997.98 |

## Labour charge

|                                        |     |          |
|----------------------------------------|-----|----------|
| Panel Beating                          | 700 | 1,000.00 |
| Spray painting                         | 600 | 1,000.00 |
| Check Wiring                           | X   | 40.00    |
| Anti rust                              | 40  | 90.00    |
| Remove and install carpet and interior | 100 | 250.00   |
| Remove and install sliding door part   | X   | 90.00    |
|                                        |     | 5,467.98 |
| Less 20%                               |     | 1,093.60 |
| Lump sum                               |     | 4,374.38 |

Tanf M 97495749  
wp 20/9/22 1pm  
C/S using after repair  
4 days  
Tanf M C/Chantoon

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                         |
|-------------------------------|-------------------------|
| Owner ID Type:                | Business                |
| Owner ID:                     | 900B                    |
| Vehicle Details               |                         |
| Vehicle No.:                  | GBK9364J                |
| Vehicle to be Exported:       | No                      |
| Intended Deregistration Date: | 19 Aug 2022             |
| Vehicle Make:                 | TOYOTA                  |
| Vehicle Model:                | HIACE VAN TURBO 5DR MT  |
| Primary Colour:               | Silver                  |
| Manufacturing Year:           | 2020                    |
| Engine No.:                   | 1KDB067449              |
| Chassis No.:                  | JTFHT02P500251169       |
| Maximum Power Output:         | -                       |
| Open Market Value:            | \$28,235.00             |
| Original Registration Date:   | 15 Jan 2021             |
| First Registration Date:      | 15 Jan 2021             |
| Transfer Count:               | 0                       |
| Actual ARF Paid:              | \$1,412.00              |
| Intended PARF Rebate Details  |                         |
| PARF Eligibility:             | No                      |
| PARF Eligibility Expiry Date: | -                       |
| PARF Rebate Amount:           | \$0.00                  |
| Intended COE Rebate Details   |                         |
| COE Expiry Date:              | 14 Jan 2031             |
| COE Category:                 | C - Goods Vehicle & Bus |
| COE Period(Years):            | 10                      |
| QP Paid:                      | \$31,502.00             |
| COE Rebate Amount:            | \$26,471.00             |
| <b>Total Rebate Amount:</b>   | <b>\$26,471.00</b>      |

The information contained herein is correct as at 19 Aug 2022

OK