

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 19.09.2022

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SLS1814U
MODEL : NISSAN QASHQAI
DATE OF ACCIDENT : 17.09.2022
TIME OF ACCIDENT : 16:15 HRS

SJNFEAJ1142025079

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rehnd</i>	1	\$ 578.80	\$ 578.80
2	REAR BUMPER SIDE BRACKET <i>Att New</i>	2	\$ 46.60	\$ 93.20
3	REAR DOOR LH <i>Dented</i>	1	\$ 1,347.90	\$ 1,347.90
4	REAR DOOR OUTER STRIP LH <i>Newer</i>	1	\$ 92.60	\$ 92.60
5	REAR DOOR LOCK CATCHER LH <i>New</i>	1	\$ 25.30	\$ 25.30
6	REAR DOOR INNER LOCK LH <i>New</i>	1	\$ 287.40	\$ 287.40
7	REAR DOOR INNER TRIM LH <i>New</i>	1	\$ 729.80	\$ 729.80
8	REAR DOOR WEATHER STRIP LH <i>New</i>	1	\$ 139.30	\$ 139.30
9	REAR DOOR PROTECTOR LH <i>Att</i>	1	\$ 190.60	\$ 190.60
10	REAR FENDER ARCH SEAL LH <i>Att</i>	1	\$ 139.60	\$ 139.60
11	REAR WHEEL RIM LH <i>Att</i>	1	\$ 897.60	\$ 897.60
12	REAR AXLE <i>New</i>	1	\$ 1,536.60	\$ 1,536.60
13	REAR SHOCK ABSORBER LH <i>New</i>	1	\$ 279.10	\$ 279.10
14	REAR WHEEL HUP LH <i>Dented</i>	1	\$ 327.60	\$ 327.60
15	REAR WHEEL HUP BEARING LH <i>Dented</i>	1	\$ 140.40	\$ 140.40

2589.60

2330.64

S.N: 650

TOTAL PRICE \$ 6,805.80
LESS 10% \$ 680.58
SUB TOTAL PRICE \$ 6,125.22

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00
2	REAR DOOR SEALANT LH <i>New</i>	1	\$ 150.00	\$ 150.00
3	REAR DOOR PROTECTOR CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00
4	REAR DOOR MOULDING CLIP (SET) <i>New</i>	1	\$ 40.00	\$ 40.00
5	REAR DOOR INNER TRIM CLIP LH (SET) <i>New</i>	1	\$ 50.00	\$ 50.00
6	REAR FENDER ARCH GARNISH CLIP LH (SET) <i>New</i>	1	\$ 50.00	\$ 50.00

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLS1814U**
 MODEL : **NISSAN QASHQAI**
 DATE OF ACCIDENT : 17.09.2022
 TIME OF ACCIDENT : 16:15 HRS

7	REAR WHEEL TYRE LH <i>not rec</i>	1	\$ 450.00	\$ 450.00	<i>X</i>
8	BRAKE OIL <i>not rec</i>	1	\$ 30.00	\$ 30.00	<i>X</i>

80

TOTAL \$ 870.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	<i>400.</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>40.</i>
4	WIRING CHECK	\$ 250.00	<i>30</i>
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>X</i>
6	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	<i>60</i>
7	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80</i>
8	TRANSFER REAR DOOR MECHANISM	\$ 80.00	<i>40</i>
9	REMOVE & REINSTALL REAR WINDOW GLASS	\$ 80.00	<i>40</i>
10	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>X</i>
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>X</i>

1340

TOTAL

\$4,560.00

TOTAL PARTS COST : \$ 6,995.22
 TOTAL LABOUR COST : \$ 4,560.00
 TOTAL REPAIR COST : \$ 11,555.22

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SLS1814U
MODEL : NISSAN QASHQAI
DATE OF ACCIDENT : 17.09.2022
TIME OF ACCIDENT : 16:15 HRS

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian L
L/S 20/09/22.

04 Days.

Total: 4400.64
L/S: 3.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: