

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0811/2022/EQ
DATE : 19-Sep-22
WIP : 42279

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/09/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN PENG CHEOK
ADDRESS : 7 SPRINGSIDE PLACE
SINGAPORE 786410

TELEPHONE : HP +65 96660442
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100488912-05
VEHICLE NO : SDR 318 S
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 10/11/2016
ENGINE NO : CZC 576661
CHASSIS NO : WAUZZZ8V3G1113363
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Sep-22
PLACE OF ACCIDENT : SIMS AVENUE TOWARDS PAYA LEBAR ROAD NEAR LOR 35
GEYLANG

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDR 318 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. RENEW ACCORDING TO DAMAGES.	S/N \$ 360.00 /	
2	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER.	S/N \$ 800.00 ?	
3	TO REMOVE AND REINSTALL CENTER CONSOLE. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, RHS CURTAIN AIRBAG, RHS DRIVER SIDE AIRBAG AND LEATHER COVER.	S/N \$ 2,800.00 /	
4	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE THE RENEWAL OF RHS REAR FENDER.	S/N \$ 600.00 /	
5	TO RENEW SOLAR FILM FOR AFFECTED GLASSES.	TBC ?	
TOTAL LABOUR CHARGES		: \$ 4,560.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDR 318 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	200.00	150
7	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ (pht)	1,400.00	/
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, LUGGAGE COMPARTMENT TRIMS.	S/N \$ (pht)	1,400.00	/
9	TO REMOVE AND RENEW RHS REAR SUSP ASSY WITH SUBFRAME.	S/N \$	2,400.00	?
10	TO SET UP AND PLACE VEHICLE ON CAR-O-LINER.	S/N \$	2,400.00	?
TOTAL LABOUR CHARGES		:	\$ 7,800.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDR 318 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
11	TO DISMANTLE REAR BUMPER. RENEW RHS REAR DOOR, CUT OUT AND WELD RHS REAR FENDER, INNER C-PILLAR - REINFORCEMENT, RHS OUTER WHEEL HOUSE AND SILL PANEL. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	8,400.00	3500
12	TO REMOVE AND REINSTALL RHS FRONT DOOR WING MIRROR ASSY.	280.00	/
13	TO RESPRAY RHS FRONT AND REAR DOORS, RHS REAR FENDER, INNER PANELS, RHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	6,250.00	3075
14	TO RENEW RHS REAR RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT.	520.00	280
15	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	384.00	/
TOTAL LABOUR CHARGES		: \$ 28,194.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDR 318 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR DOOR - RH / <i>OK</i>	1	\$	3,265.00	
2	REAR OUTER DOOR SEAL - RH - <i>OK</i>	1	\$	179.00	
3	BONDING AGENT - <i>OK</i>	1	\$	51.00	
4	CLEANING SOLUTION - <i>OK</i>	1	\$	74.00	
5	APPLICATOR - <i>OK</i>	1	\$	9.00	
6	REAR DOOR CATCH - RH ?	1	\$	105.00	
7	REAR DOOR INNER SEAL - RH - <i>OK</i>	1	\$	213.00	
8	REAR DOOR ATTACHMENT PARTS ?	1	\$	134.00	
9	REAR DOOR HANDLE - RH X <i>R</i>	1	\$	398.00	
10	REAR DOOR SLIDE VALVE - R H ?	1	\$	25.00	
11	REAR DOOR HOUSING - RH ?	1	\$	58.00	
12	REAR DOOR MOUNTING BAR - RH ?	1	\$	182.00	
13	REAR DOOR BOWDEN CABLE ?	1	\$	58.00	
14	REAR DOOR BOWDEN CABLE HOLDER ?	1	\$	4.00	
15	REAR DOOR LOCK - RH ?	1	\$	630.00	
16	REAR DOOR STRIKER ?	1	\$	69.00	
17	REAR DOOR BOWDEN CABLE ?	1	\$	43.00	
18	REAR WINDOW GUIDE - RH ?	1	\$	467.00	
19	REAR WINDOW GUIDE TRIM STRIP - RH ?	1	\$	250.00	
20	REAR WINDOW SLOT SEAL TRIM STRIP - RH ?	1	\$	331.00	
SUB TOTAL SPARE PARTS		:	\$	6,545.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDR 318 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	REAR DOOR PANEL INNER COVER - RH ?	1	\$	28.00	
22	REAR DOOR PANEL - RH <i>mt</i> ?	1	\$	1,831.00	
23	REAR DOOR WINDOW FRAME TRIM - RH ?	1	\$	134.00	
24	REAR WINDOW REGULATOR - RH ?	1	\$	286.00	
25	REAR WINDOW GUIDE RAIL - RH ?	1	\$	58.00	
26	REAR DOOR CONTROL UNIT ?	1	\$	443.00	
27	REAR WINDOW REGULATOR MOTOR - RH ?	1	\$	300.00	
28	REAR SIDE PANEL - RH / <i>OP</i>	1	\$	3,662.00	
29	REAR WHEEL HOUSING LINER / <i>CR4</i>	1	\$	260.00	
30	REAR WHEEL HOUSING LINER ATTACHMENT PARTS / <i>ne</i>	1	\$	93.00	
31	REAR WINDOW / <i>ne</i>	1	\$	905.00	
32	REAR WINDOW PRIMER / <i>ne</i>	1	\$	22.00	
33	REAR SIDE WINDOW - RH / <i>ne</i>	1	\$	635.00	
34	REAR SIDE WINDOW PRIMER / <i>ne</i>	1	\$	22.00	
35	REAR WHEEL HOUSING INNER - RH ?	1	\$	673.00	
36	C-PILLAR PLATE - LOWER ?	1	\$	15.00	
37	C-PILLAR LOWER REINFORCEMENT - RH ?	1	\$	211.00	
38	C-PILLAR THREADED PLATE - RH ?	1	\$	36.00	
39	C-PILLAR PLATE - LOWER ?	1	\$	15.00	
40	C-PILLAR SIDE MEMBER - RH ?	1	\$	434.00	
SUB TOTAL SPARE PARTS		:	\$	10,063.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDR 318 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	REAR WHEEL HOUSING TRIM - RH / CR4	1	\$	149.00	
42	ROOF LINER / CR4	1	\$	2,113.00	
43	HEAD AIRBAG UNIT / BR	1	\$	2,069.00	
44	REAR BACKREST COVER - RH (FLY RH) / BR	1	\$	2,449.00	
45	SIDE AIRBAG UNIT / BR	1	\$	1,688.00	
46	THREE-POINT AUTOMATIC SEAT BELT - LH / RH - JWS	2	\$	2,454.00	
47	SEAT BELT HEIGHT ADJUSTER - LH / RH ?	2	\$	430.00	
48	AIRBAG CONTROL UNIT / MC	1	\$	1,923.00	
49	AIRBAG CRASH SENSOR ?	1	\$	449.00	
50	FRONT GRAB HANDLE - LH / RH ?	2	\$	326.00	
51	REAR GRAB HANDLE - LH / RH ?	2	\$	326.00	
52	REAR ALUMINIUM RIM - RH / MC	1	\$	1,303.00	
53	REAR ALUMINIUM RIM RUBBER VALVE - RH / MC	1	\$	8.00	
54	REAR CROSS MEMBER ?	1	\$	1,844.00	
55	REAR CROSS MEMBER - FRONT ?	2	\$	200.00	
56	REAR CROSS MEMBER - REAR ?	2	\$	200.00	
57	REAR WHEEL BEARING HOUSING - RH ?	1	\$	666.00	
58	REAR WHEEL BEARING HOUSING BONDED RUBBER BUSH ?	1	\$	31.00	
59	REAR WHEEL BEARING ASSEMBLY PARTS ?	1	\$	486.00	
60	REAR TRACK ROD - RH ?	1	\$	119.00	
SUB TOTAL SPARE PARTS		:	\$	19,233.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDR 318 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	REAR LOWER ARM - RH ?	1	\$	347.00
62	REAR WISHBONE - RH ?	1	\$	300.00
63	BONDED RUBBER BUSH ?	1	\$	31.00
64	REAR UPPER WISHBONE - LH / RH ?	1	\$	300.00
65	REAR GAS SHOCK ABSORBER - RH ?	1	\$	276.00
66	ACRYLIC SEALER ? - ne	S/N	\$	180.00
67	CAVITY WAX - ne	S/N	\$	140.00
68	STONE CHIPS - ne	S/N	\$	180.00
69	METAL FILLER POWDER - ne	S/N	\$	280.00
70	REAR WINDSCREEN SEALANT - ne	S/N	\$	200.00
71	1/4 GLASS SEALANT - ne	S/N	\$	100.00
72	SUNDRIES ?		\$	900.00
TOTAL SPARE PARTS		:	\$	39,075.00
TOTAL LABOUR CHARGES		:	\$	28,194.00
GRAND TOTAL		:	\$	67,269.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve CLKK)
20/9/12, 4.45 p.m.

OD 14 AL
EXC 11-?
P/P
Lg BL y
20 ~~11~~ 12

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT