

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0809/2022/EQ
DATE : 19-Sep-22
WIP : 42312

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/09/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR YAP ZONG XING, ERIC
ADDRESS : 21 ANCHORVALE CRESENT
#09-24
SINGAPORE 544654
TELEPHONE : HP +65 90102301
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210154384
VEHICLE NO : SKM 5128 J
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 28/12/2021
ENGINE NO : DEM 034426
CHASSIS NO : WAUZZZF5XNA002843
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Sep-22
PLACE OF ACCIDENT : CTE BEFORE BRADDELL EXIT, FIRST LANE

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKM 51281

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY, FRONT PARKING AID AND FRONT CAMERA ASSY.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE.	150 x 2 S/N \$ 800.00 500	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND CHARGED AIR COOLER. RENEW IF NECESSARY. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO PRESSURISE COOLING SYSTEM.	S/N \$ 1,600.00 /	
4	TO CARRY OUT VACCUM AND REGAS FOR R1234.	S/N \$ 1,200.00 /	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHTS. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	1.5 S 6,400.00 1750 3.5 x 500	
TOTAL LABOUR CHARGES		: \$ 10,480.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKM 51281


S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS AND WING MIRROR ASSY FOR BOTH DOORS REPAIR. RENEW BOTH FRONT DOOR WINDOW SLOT SEAL.	S/N \$ 720.00 <i>28 x 1</i>	<i>560</i>
7	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH A-PILLARS, AND BOTH FRONT DOORS.	\$ 6,800.00 <i>6 x 350</i>	<i>7300</i>
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 18,192.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5KM 51281

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER / <i>OK</i>	1	\$	2,493.00	
2	FRONT BUMPER GRILLE - CENTER ?	1	\$	219.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ?	1	\$	293.00	
4	RADIATOR GRILLE STRIKER PLATE / <i>BR</i>	1	\$	293.00	
5	FRONT BUMPER AIR GUIDE GRILLE - LH ?	1	\$	151.00	
6	FRONT BUMPER OUTER GRILLE HOLE COVER - LH ?	1	\$	54.00	
7	FRONT BUMPER AIR GUIDE GRILLE - RH ?	1	\$	151.00	
8	FRONT BUMPER AIR GUIDE GRILLE TRIM COVER - RH ?	1	\$	54.00	
9	FRONT BUMPER TRIM - CENTER ?	1	\$	127.00	
10	RADIATOR GRILLE / <i>BR</i>	1	\$	1,881.00	
11	"360" CAMERA COVER / <i>CVI</i>	1	\$	141.00	
12	"360" CAMERA BRACKET / <i>BR</i>	1	\$	19.00	
13	"360" CAMERA SECURING PLATE / <i>BR</i>	1	\$	12.00	
14	FRONT CAMERA ?	1	\$	1,264.00	
15	FRONT CAMERA ADAPTER CABLE ?	1	\$	219.00	
16	FRONT CAMERA ADAPTER CABLE LOOM ?	1	\$	319.00	
17	FRONT BUMPER FOAM FILLER PIECE / <i>OK</i>	1	\$	163.00	
18	LOCK CARRIER BRACKET / <i>BR</i>	1	\$	154.00	
19	FRONT BUMPER REINFORCEMENT BEAM / <i>BT</i>	1	\$	899.00	
20	LOCK CARRIER SUPPORT - LH / RH / <i>MC</i>	2	\$	64.00	
SUB TOTAL SPARE PARTS			:	\$ 8,970.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKM 51281

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT BUMPER TOP COVER / CRV	1	\$	143.00	
22	CAUTION SIGN STICKER / MC	1	\$	16.00	
23	AIR CONDITIONER STICKER / MC	1	\$	9.00	
24	FRONT FENDER - LH / RH / MC	1 2	\$	2,378.00	
25	FRONT FENDER ATTACHMENT PARTS - LH / RH ?	2	\$	110.00	
26	FRONT FENDER CLOSING ELEMENT - LH / RH ?	2	\$	166.00	
27	FRONT FENDER BRACKET - LH / RH ? / MC	1 2	\$	82.00	
28	FRONT FENDER RIVET / MC	10	\$	38.00	
29	FRONT FENDER BRACE - LH / RH ?	2	\$	264.00	
30	FRONT FENDER LEDGE COVER - LH / RH SHORT / BR	2	\$	36.00	
31	FRONT FENDER UPPER SEAL - LH / RH LONG / MC	1 2	\$	80.00	
32	BONNET / MC	1	\$	3,491.00	
33	BONNET ATTACHMENT PARTS X	1	\$	128.00	
34	BONNET IMPACT PROTECTION - CENTER / RH / LH / MC	3	\$	93.00	
35	BONNET HINGE - LH / RH ?	2	\$	932.00	
36	BONNET LOCK - LH / RH ?	2	\$	455.00	
37	BONNET STRIKER - LH / RH ?	2	\$	112.00	
38	BONNET BOWDEN CABLE - CENTER ?	1	\$	64.00	
39	BONNET SOUND ABSORBER X	1	\$	382.00	
40	BONNET BOWDEN CABLE - CENTER ?	1	\$	64.00	
SUB TOTAL SPARE PARTS		:	\$	9,043.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKM 51281

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HEADLIGHT - LH / RH <i>OK</i>	②	\$	16,344.00
42	HEADLIGHT POWER MODULE ?	1	\$	850.00
43	LIFT CYLINDER - LH / RH ?	2	\$	434.00
44	LIFT CYLINDER BRACKET - LH / RH ?	2	\$	34.00
45	LIFT CYLINDER CORRUGATED PIPE ?	1	\$	107.00
46	LOCK CARRIER MOUNTING ?	1	\$	1,478.00
47	RADIATOR AIR GUIDE - LH / RH INNER ?	2	\$	72.00
48	RADIATOR AIR GUIDE - LH / RH OUTER ?	2	\$	38.00
49	RADIATOR AIR GUIDE - UPPER ?	1	\$	19.00
50	OUTSIDE TEMPERATURE SENSOR BRACKET <i>OK</i>	1	\$	21.00
51	EXTERNAL TEMPERATURE SENSOR ?	1	\$	64.00
52	A/C CONDENSER <i>OK</i>	1	\$	683.00
53	A/C REFRIGERANT PRESSURE SENSOR ?	1	\$	206.00
54	A/C SERVICE VALVE CORE ?	1	\$	53.00
55	CHARGE AIR COOLER <i>X</i>	1	\$	654.00
56	CHARGE AIR COOLER SEAL RING <i>X</i>	1	\$	95.00
57	RADIATOR ?	1	\$	699.00
58	RADIATOR SECURING PIN - UPPER LH / RH ?	2	\$	6.00
59	RADIATOR SLEEVE - UPPER LH / RH ?	2	\$	19.00
60	RADIATOR GROMMET - UPPER LH / RH ?	2	\$	22.00
SUB TOTAL SPARE PARTS		:	\$ 21,898.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKM 51281

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR RUBBER BUSH - LOWER LH / RH 1	2	\$	20.00
62	RADIATOR RUBBER BUSH - LOWER LH / RH 2	2	\$	28.00
63	READY-MIX COOLANT 1	4	\$	198.00
64	FRONT FENDER CHROME TRIM - LH / RH ✓ Mc (2)	2	\$	342.00
65	FRONT DOOR CHROME TRIM - LH / RH ✓ Mc (2)	2	\$	342.00
66	FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH X	2	\$	892.00
67	FRONT NO PLATE ✓ MIS S/N	S/N	\$	100.00
68	SUNDRIES 1		\$	800.00
TOTAL SPARE PARTS		:	\$	42,633.00
TOTAL LABOUR CHARGES		:	\$	18,192.00
GRAND TOTAL		:	\$	60,825.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Star (LKK)
20/9/22. 4.30 pm

OP- M AL
EXcess - ?
PIP
by BEL y
8 Lys

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT