Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.

Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Chew, Yvonne Date: 21 Sep 2022

Preliminary Advice

Vehicle No : SNB4607Y Accident Date : 16/09/2022 Make : AUDI A5 Policy No. : 7210091715-

01

: 14

: S\$0.00

Assignment

Date

Excess : 21/09/2022

Est. Duration of

Date of Inspection

Repair

Inspection At: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

: 20/09/2022

SINGAPORE 408699

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 47,513.00 **Revised Amount** :S\$ 35,713.00 Check Items (Estimated) :S\$ 2,357.00 Total :S\$ 38,070.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 207,000.00 COE / PARF Rebate :S\$ 87,033.00 Salvage Value :S\$

Margin for Repair :S\$ 119,967.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.