



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

date x time 21/9/11:35am
1st survey 21/9 1pm
dismantle 21/9 1pm
194N
After repair 27/9 3:30pm

Elaine typist

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref: CS3/ASM22009271/Svy3	
8 SHENTON WAY #24-01		Date: 21/09/2022	
AXA TOWERSINGAPORE 068811		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHA 507E	Veh. Inspected	SMV 319L
Policy No.		Coverage (\$)	0.00
Claim No.	S2M04BAG	Excess (\$)	0.00
Assign From	ANG YVONNE	Assign Date	21/09/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/09/2022	Inspection Date	21/09/2022
Survey held at	365 AUTOMOTIVE PTE LTD 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @KB SINGAPORE 417800		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			