

ASS. REC. BY:

REF:

ASM / 22009272/K843

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

813k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

10/23

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STK 8306C

Yr Regn:

10, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Aiti's

C.C.

1598

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR0538EE108171452

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / SRim / STD A/Rim or

Tyre Size:

F: Wind force

R: Wind force 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

11/9/22

D.O.A.

21/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/9 Unable to find car key at time of survey, can't open door.

11/10 / 11/10/22 @ 8000 Cash 19/10/22 (red 8 11161.83, 58%)

Date/Time, File Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

10

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S - RS. SI

F. & S.

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Smart Claims - TP

Lump Sum / L.B.F. (\$

8000

KIEN CHEONG AUTOMOTIVE

BLK 9 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-26 SINGAPORE 575644

H/P : 8125 9406 FAX : 64550902

Not Authorized
1/100 @ 8000p. max
Permy After Paim
10days

The Motor Claims Dept.

AXA Insurance

(LKK)

DATE : 20/9/2022

VEHICLE NO : SJK 6306 C

MAKE/MODEL : Toyota Altis

ACC DATE : 17/9/2022

ESTIMATE

Page . 1 .

S/N	PC	List Items	AMOUNT SS
1	1	Front LH door	1,280.30 X
2	1	Front LH door moulding	169.30 X
3	1	Front RH kunkle 545.50	666.10 7
4	1	Front RH lower arm 602.50	776.40 7
5	1	Front RH wheel bearing	121.90 7
6	1	Front RH shock absorber 401.80	464.70 7
7	1	Front RH shock absorber mounting	230.80 7
8	1	Front RH shock absorber stopper	29.10 7
9	1	Rear LH door 980.40	1,140.10 7
10	1	Rear LH door outer moulding	35.60 X
11	1	Rear LH door ounter handle	115.20 X
12	2	Rear LH door hinges @\$65.00	130.00 7
13	1	Rear LH door checker	42.00 X
14	1	Rear LH door inner lock 361.20	425.20 7
15	1	Rear LH door lock catch	58.30 X
16	1	Rear LH door w/strip	225.50 7
17	1	Rear LH door regulator gear	231.70 7
18	1	Rear LH door regulator motor	429.40 7
19	1	Rear LH door inner trim 715.30	854.30 7
20	1	Rear LH door frame sticker P.C.	347.80 7
21	1	LH door side skirting	685.60 7
22	1	LH side rocker panel	688.30 7
24	1	Rear LH fender	529.80 7
25	1	Rear LH fender inner panel	290.60 X
26	1	Rear LH fender inner shield	68.60 X
27	1	Rear LH petrol cover	85.60 X
28	1	Rear bumper	647.90 X
30	1	Rear Axle beam 1535	3,975.40 7
31	2	Rear wheel bearing with hub @856.20 C 601.20	1,712.40 7
32	2	Rear shock absorber @\$331.30	662.60 7
33	2	Rear shock absorber mounting @\$85.00	170.00 7
34	2	Rear shock absorber stopper @\$49.30	98.60 7
			17,389.10
			(4,347.28)
			13,041.82

Less 25%

KIEN CHEONG AUTOMOTIVE

BLK 9 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-26 SINGAPORE 575644

H/P : 8125 9406 FAX : 64550902

The Motor Claims Dept.

AXA Insurance

(LKK)

DATE : 20/9/2022

VEHICLE NO : SJK 6306 C

MAKE/MODEL : Toyota Altis

ACC DATE : 17/9/2022

ESTIMATE

S/N PC Special Items :

Page . 2 .

AMOUNT S\$

1	1	Rear LH door inner trim clip (1set)
2	1	Rear LH fender inner shield clip (1set)
3	2-3	Rear tyres
4	3	Tyre rims
5	1	Rear bumper clips (1 set)

na	30.00	✓
na	30.00	x
360sn	750.00	908line
na	1,000.00	750in
na	30.00	x
	<u>1,840.00</u>	

Labour Charges :

1	Wheel alighment
2	To check up electrical wiring
3	To remove , refix door mechanisms
4	To remove, refix front and rear under carriage
5	Anti rust
6	To respray painting & etc
7	Panel beat, remove and replacing above parts

100.00	80d
80.00	20d
250.00	60d
450.00	38d
100.00	60d
1,800.00	120d
1,500.00	120d
<u>4,280.00</u>	

Total Repair Cost

19,161.83



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



**SINGAPORE
POLICE FORCE**



T/20220917/2052

1 of 3

Report No. T/20220917/2052

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-150 SINGAPORE
570025
Tel No: 1800-4529999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
17/09/2022 18:02

Video Report No.
D/20220917/0058

Station Diary No.:
31

Informant's Particulars

Name of Informant:
SIM KIN LYE

Address:
APT BLK 88 TELOK BLANGAH HEIGHTS #15-357
SINGAPORE 100888

Contact No.:

Mobile: 84441010

Home/Office:

Email:

ID Type / ID No.:

NRIC NO / S0060085G

Nationality:

SINGAPORE CITIZEN

Sex:

Male

Age:

72

Date of Birth:

10/01/1950

Type of Informant:
Driver

Race:

Chinese

Language:

Institution / School Name:

Occupation:

MECHANIC

Driving Licence Information:

Class: 2B,2A,2,3

Date of Expiry:

General Information of the Accident

Type of
Accident:

Injury

Attended by Police

Drink

Drive:

No

Date/Time of

Accident:

17/09/2022 10:40

Type of Location:

Location:

TELOK BLANGAH HEIGHTS

Weather:

Road Surface:

Road Speed Limit:

Traffic Flow:

Traffic Control:

Traffic Volume:

Type of Collision:

Anyone conveyed by
ambulance:

Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passengers
SHA3404Z	Taxi					
JK6306C	Car	TOYOTA	COROLLA ALTIS 1.6	Black	Seriously Damaged	0
W9498L	Car		AUTO		Seriously Damaged	0
					Seriously Damaged	0



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Thomson NP
25 Sin Ming Road #01-180 SINGAPORE
570828
Tel No: 1800-4529999



T/20220917/2052

3 of 3

Report No. T/20220917/2052

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:

E /
SGT 3 MUHAMMAD RIDZUAN
BIN ABDUL RAHMAN

Signature Of Interpreter:
Not applicable

Signature Of Informant:

Date/Time
17/09/2022 16.02

Classification Of Case:

Officer In Charge Of Case:

TP / GIT /
SGT 3 MUHAMMAD SYARIFUDDIN
MUHAMMAD AJMAIN
Contact No.: 65476367

NP168