

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI22009275/KNCQ2**Date:** 07/11/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MP002395	
Claimant Vehicle No :	SHC5622L	Insured Vehicle No :	GBD8497C	
Date of Loss:	01/09/2022	Nature of Claim:	TP	Claim No: M2204741

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5622L	Engine No:	2ZR2G79587
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Chassis No:	JTDKB3FU603091420
Reg. Date:	28/08/2020 (Man. Year: 2020)	Odometer:	251867 km
Colour:	Metallic White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 9 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Wanli 9 mm	Rear Right Side:	Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,215.75	2,064.45	5,151.30	71.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,300.00	1,125.00	4,175.00	78.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,515.75	3,189.45	9,326.30	74.52
+ GST 7.00/7.00% (S\$)	876.10	223.26	652.84	74.52
Nett Amount (S\$)	13,391.85	3,412.71	9,979.14	74.52

INSPECTION

Date of Assignment:	22/09/2022	Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
Date Inspected:	19/09/2022	Inspected At: 2, Ang Mo Kio Street 63
Estimated Period of Repair:	3.0 days	Singapore 569111

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2022)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5622L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
3	1		*GUARD ,REAR BUMPER ,CENTER	Dented / Cut	374.50 FL	*374.50 FL
4	1		*SEAL ,REAR BUMPER SIDE ,LH	Serviceable	118.30 FL	*- FL
5	1		*SEAL ,REAR BUMPER SIDE ,RH	Serviceable	118.30 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	132.60 FL	*- FL
7	1		*COVER ,REAR BUMPER ,LOWER	Serviceable	22.00 FL	*- FL
8	1		*COVER ,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
9	1		*COVER ,FLOOR UNDER NO.2 (RH)	Serviceable	241.90 FL	*- FL
10	1		*COVER ,FLOOR UNDER NO.1 (LH)	Serviceable	175.10 FL	*- FL
11	1		*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
12	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
13	1		*PANEL SUB-ASSY ,BACK DOOR	Repair	1,147.80 FL	*- FL
14	1		*SPOILER SUB-ASSY ,REAR	Cracked	1,575.40 FL	*1,575.40 FL
15	1		*PLATE ,LUGGAGE COMPARTMENT DOOR NAME NO.2	Necessary	54.60 FL	*54.60 FL
16	1		*PLATE ,BACK DOOR NAME NO.1	Necessary	54.60 FL	*54.60 FL
17	1		*ORNAMENT SUB-ASSY ,BACK DOOR	Necessary	47.90 FL	*47.90 FL
18	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Repair	913.60 FL	*- FL
19	1		*BOARD ASSY ,BACK DOOR TRIM	Serviceable	259.20 FL	*- FL
20	1		*WEATHERSTRIP BACK DOOR	Serviceable	372.30 FL	*- FL
21	1		*STAY ,ASSY ,BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
22	1		*STAY ,ASSY ,BACK DOOR ,RH	Serviceable	242.50 FL	*- FL
23	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
24	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- FL
25	1		*REAR SPOILER CLIP	Not Necessary	65.00 FS	*- FS
26	1		*REAR BUMPER SIDE CLIP	Not Necessary	60.00 FS	*- FS
27	1		*BOOT STICKER TRANS-CAB	Necessary	100.00 FS	*30.00 FS
28	1		*BOOT STICKER TEL NO	Necessary	100.00 FS	*30.00 FS
29	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
30	1		*SET REAR BUMPER CLIP	Necessary	85.00 FS	*60.00 FS
31	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,226.00	2,712.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,010.25	648.15
Total Parts (\$\$)	7,215.75	2,064.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,800.00	400.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	660.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			5,300.00	1,125.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >