

Not Notion
 Presumy Bk paint

AAD2208-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5622L

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

19 SEP 2022

SHC5622L

JTDKB3FU603091420

200303878K

TOYOTA

PRIUS GEN 4

01/09/2022

GBD8497C/TOKIO

28/08/2020

	PART
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	GUARD, REAR BUMPER, CENTER
1	SEAL, REAR BUMPER SIDE, LH
1	SEAL, REAR BUMPER SIDE, RH
1	RETAINER, REAR BUMPER SIDE, RH
1	COVER, REAR BUMPER, LOWER
1	COVER, DECK TRIM, REAR
1	COVER, FLOOR UNDER, NO.2 (RH)
1	COVER, FLOOR UNDER, NO.1 (LH)
1	COVER, REAR FLOOR (CTR)
1	PANEL SUB-ASSY, BODY LOWER BACK
1	PANEL SUB-ASSY, BACK DOOR
1	SPOILER SUB-ASSY, REAR
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
1	PLATE, BACK DOOR NAME, NO.1
1	ORNAMENT SUB-ASSY, BACK DOOR
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1	BOARD ASSY, BACK DOOR TRIM
1	WEATHERSTRIP, BACK DOOR
1	STAY ASSY, BACK DOOR, LH
1	STAY ASSY, BACK DOOR, RH
1	HINGE ASSY, BACK DOOR, LH
1	HINGE ASSY, BACK DOOR, RH

	LIST
\$	Bu 485.60 ✓
\$	332.70 ?
\$	Od / M 374.50 ✓
\$	Sn 118.30 X
\$	Sn 118.30 X
\$	Sn 132.60 X
\$	Sn 22.00 X
\$	Sn 126.70 X
\$	Sn 241.90 X
\$	Sn 175.10 X
\$	Sn 229.90 X
\$	R 651.00 X
\$	R 1,147.80 X
\$	cm 1,575.40 ✓
\$	ru 54.60 ✓
\$	ru 54.60 ✓
\$	ru 47.90 ✓
\$	Scn R Bu 913.60 X
\$	Sn 259.20 X
\$	Sn 372.30 X
\$	Sn 242.50 X
\$	Sn 242.50 X
\$	R 61.00 X
\$	R 61.00 X
TOTAL	\$ 8,041.00
25%	\$ 2,010.25
	\$ 6,030.75

Special Nett

1 REAR SPOILER CLIP

\$ ru 65.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2208-**SHC5622L**

1 REAR BUMPER SIDE CLIP	\$	nn	60.00	X
1 BOOT STICKER TRANSCAB	\$	nn	100.00	305N
1 BOOT STICKER TEL NO	\$	nn	100.00	305N
1SET PARKING AID	\$	nn	700.00	X
1SET REAR BUMPER CLIP	\$	nn	85.00	605N
1 REAR BUMPER RETAINER CLIP	\$	nn	75.00	X
TOTAL	\$		1,120.00	
TOTAL PARTS	\$		7,150.75	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,800.00	4001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	6601
To reinstall rear bumper parking sensor.	\$		170.00	501
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	151
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	nn	170.00	X
TOTAL	\$		5,300.00	
Over All Total	\$		12,450.75	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

(PART-BY-PART) Repair Days**20 Days****3 days**