

Not Notified
Resumy B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5622L

AAD2208-

3189.45

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

19 SEP 2022

SHC5622L

JTDKB3FU603091420

200303878K

TOYOTA

PRIUS **GEN 4**

01/09/2022

GBD8497C/TOKIO

28/08/2020

PART		LIST	
1	COVER, REAR BUMPER	\$	<i>Bu</i> 485.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>R</i> 332.70 X
1	GUARD, REAR BUMPER, CENTER	\$	<i>Od / W</i> 374.50 ✓
1	SEAL, REAR BUMPER SIDE, LH	\$	<i>Sn</i> 118.30 X
1	SEAL, REAR BUMPER SIDE, RH	\$	<i>Sn</i> 118.30 X
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>Sn</i> 132.60 X
1	COVER, REAR BUMPER, LOWER	\$	<i>Sn</i> 22.00 X
1	COVER, DECK TRIM, REAR	\$	<i>Sn</i> 126.70 X
1	COVER, FLOOR UNDER, NO.2 (RH)	\$	<i>Sn</i> 241.90 X
1	COVER, FLOOR UNDER, NO.1 (LH)	\$	<i>Sn</i> 175.10 X
1	COVER, REAR FLOOR (CTR)	\$	<i>Sn</i> 229.90 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>R</i> 651.00 X
1	PANEL SUB-ASSY, BACK DOOR	\$	<i>R</i> 1,147.80 X
1	SPOILER SUB-ASSY, REAR	\$	<i>cm</i> 1,575.40 ✓
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	<i>nn</i> 54.60 ✓
1	PLATE, BACK DOOR NAME, NO.1	\$	<i>nn</i> 54.60 ✓
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	<i>nn</i> 47.90 ✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	<i>scr</i> \$	<i>R Sn</i> 913.60 X
1	BOARD ASSY, BACK DOOR TRIM	\$	<i>Sn</i> 259.20 X
1	WEATHERSTRIP, BACK DOOR	\$	<i>Sn</i> 372.30 X
1	STAY ASSY, BACK DOOR, LH	\$	<i>Sn</i> 242.50 X
1	STAY ASSY, BACK DOOR, RH	\$	<i>Sn</i> 242.50 X
1	HINGE ASSY, BACK DOOR, LH	\$	<i>R</i> 61.00 X
1	HINGE ASSY, BACK DOOR, RH	\$	<i>R</i> 61.00 X
TOTAL		\$	8,041.00
25%		\$	2,010.25
		\$	6,030.75

Special Nett

1	REAR SPOILER CLIP	\$	<i>nn</i> 65.00 X
---	-------------------	----	-------------------

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5622L**AAD2208-**

1 REAR BUMPER SIDE CLIP	\$	nn	60.00	X
1 BOOT STICKER TRANSCAB	\$	nn	100.00	30sn
1 BOOT STICKER TEL NO	\$	nn	100.00	30sn
1SET PARKING AID	\$	sn	700.00	X
1SET REAR BUMPER CLIP	\$	nn	85.00	60sn
1 REAR BUMPER RETAINER CLIP	\$	nn	75.00	X
TOTAL	\$		1,120.00	
TOTAL PARTS	\$		7,150.75	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,800.00	4001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	6601
To reinstall rear bumper parking sensor.	\$		170.00	501
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	151
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	nn	170.00	X
TOTAL	\$		5,300.00	
Over All Total	\$		12,450.75	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

(PART-BY-PART) Repair Days**20 Days****3 days**