

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5491SLKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

AAD2209-

Acknowledged by Repairer

Signature:

Date:

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD5491S

JTDKB3FU103077134

200303878K

TOYOTA

PRIUS

16/09/2022

GBA3022M/TOKIO

04/12/2018

PART

- 1 MIRROR ASSY, OUTER REAR VIEW, LH

LIST

	\$	1,339.30
TOTAL	\$	1,339.30
25%	\$	334.83
	\$	1,004.48 ✓

LABOURTo remove and refit interior fittings, trimings, garnish, fittings
and other, to enable repair.\$ 380.00 *x an*

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 *200 ✓*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 *x an*

To Check Electrical Lighting Concerned.

\$ 170.00 *x an***TOTAL \$ 2,190.00****Over All Total \$ 3,194.48**

200

(LUMP SUM) Repair Days

10 days

1204.48

L/S - 963.58
= 950

1 Day
Lump sum repair
After repair photos
Gue Qi Y
16/9/22