



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300643

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 02/02/2023
Reference CC6/CTI22009282/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SNB 1255Z
Insured Veh. SLP 8456P
Claim No. SNM22D206624/C02
Policy No. DMPCSNW00145992203
Accident Date 16/09/2022
Inspection Date 21/09/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22009282/Upa3q2 Date: 02/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLP 8456P	Veh. Inspected	SNB 1255Z	
Policy No.	DMPCSNW00145992203	Coverage (\$)	0.00	
Claim No.	SNM22D206624/C02	Excess (\$)	0.00	
Assign From		Assign Date	21/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	CITROEN DS7 CROSSBACK (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	VR1J45GFULY050181	Colour	GREY	
Odometer	26962 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	YOKOHAMA	7 mm	
L/H Front Tyre	235/55 R18	YOKOHAMA	7 mm	
R/H Rear Tyre	235/55 R18	YOKOHAMA	7 mm	
L/H Rear Tyre	235/55 R18	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/09/2022	Inspection Date	21/09/2022	
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 1255Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER ASSY TOP & LOWER (N)	DEFORMED / TORN	2,885.00	2,393.00
1	REAR BUMPER MOULDING (N)	TWISTED	282.00	255.00
2	REAR BUMPER TOW COVER @\$55.00 (N)	NOT NECESSARY	110.00	-
2	REAR BUMPER LAMPS - R/L @\$435.00 (N)	O/S SCRATCHED	870.00	223.00
4	REAR BUMPER PDC SENSOR @\$285.00 (N)	SHORTED (1PC ONLY)	1,140.00	231.00
1	REAR BUMPER PDC SENSOR WIRE HARNESS (N)	NOT NECESSARY	680.00	-
2	REAR BUMPER SIDE BRACKETS - R/L @\$115.00 (N)	O/S CRACKED	230.00	115.00
1	REAR BUMPER TOP GUIDE - CTR (N)	CRACKED	286.00	286.00
2	REAR BUMPER SIDE GUIDE - R/L @\$135.00 (N)	O/S CRACKED	270.00	135.00
1	REAR BUMPER REINFORCEMENT (N)	BENT	1,265.00	670.00
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	1,055.00	-
2	REAR EXHAUST CHROME TRIMS - R/L @\$485.00 (N)	NOT NECESSARY	970.00	-
2	REAR EXHAUST CHROME TRIMS BRACKETS @\$95.00 (N)	NOT NECESSARY	190.00	-
1	REAR EXHAUST INSULATOR (N)	NOT NECESSARY	225.00	-
2	REAR FENDER PROTECTOR - R/L @\$445.00 (N)	NOT NECESSARY	890.00	-
	LESS 10% DISCOUNT		-1,134.80	-430.80
			10,213.20	3,877.20
	<u>LABOUR</u>			
	TO CHECK REAR ELECTRICAL WIRING.		50.00	20.00
	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR.		120.00	60.00
	TO TUFF KOTE.	NOT NECESSARY	50.00	-
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS.		800.00	500.00
	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	550.00
			1,820.00	1,130.00
	GRAND TOTAL		12,033.20	5,007.20



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00
---	--	--	----------

Report Ref No. CC6/CTI22009282/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNB 1255Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNB 1255Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNB 1255Z

RE-INSPECTION

