

# BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

## Estimate Quotation

Xiao Chan

Quotation No	Spe 001/2022
Date	19/9/2022
Vehicle No	SLU2597D
Make / Model	Mazda 3

To: China Taiping Insurance (S) Pte Ltd

Address: 3 Anson Rd, #16-00 Springleaf Tower, Singapore 079909

Qty	DESCRIPTION	UNIT	Amount
	<b>Items</b>		
1 pc	front bumper <i>torn</i>		\$ 985.00
1 set	front bumper side retainer <i>crack</i>		\$ 63.00
1 pc	o/s headlamp <i>crack</i>		\$ 1,550.00
1 pc	o/s fog lamp <i>3432</i>		\$ 275.00
1 pc	o/s fog lamp garnish		\$ 98.00
1 pc	o/s front fender <i>Dented</i>		\$ 579.00
1 pc	o/s fender inner shield <i>Del-d</i>		\$ 255.00
	<b>Labour Charge</b>		
1	to dismantle damaged parts, panel beat, repair		\$ 800.00
2	to putty and spray painting on affected area		\$ 800.00
3	anti rust		\$ 50.00
4	wiring check		\$ 80.00
	<b>Subtotal:</b>		\$ 5,535.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

Adrian King  
1/5 20/09/22

04 Days

Total: 3755.60

1/5: 3K

3K