

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

not Authorized
21/09/22
1/s # 21,200/
7 days.

VEHICLE No: SMU 681U

NETT ITEM

1PC	BONNET	BuL	3425	\$5,055.00	✓
1PC	BONNET INNER CENTRE SEAL	ner	78	\$82.00	✓
1PC	BONNET INNER SEAL N/S	ner	60	\$70.00	✓
1PC	BONNET INSULATOR	^^		\$380.00	X
1SET	BONNET INSULATOR CLIPS	^^		\$80.00	X
1PC	BONNET INNER LOCK	Yw1	245	\$650.00	✓
1PC	FRONT BUMPER	Dis	2377	\$2,697.00	✓
2PCS	FRONT BUMPER SIDE RETAINERS @\$250.00	n/s cre	115	\$500.00	1PC
1PC	FRONT BUMPER CENTRE GRILLE	tw1	222	\$420.00	✓
1PC	FRONT BUMPER LOWER CENTRE GRILLE	tw1	180	\$399.00	✓
1PC	FRONT BUMPER SPONGE	Torn	182	\$416.00	✓
1PC	FRONT BUMPER REINFORCEMENT	Burf	899	\$1,515.00	✓
1PC	FRONT BUMPER REINFORCEMENT LOWER BRACKET	Burf	205	\$350.00	✓
1PC	FRONT BUMPER REINFORCEMENT LOWER	Burf	480	\$1,100.00	✓
1PC	FRONT BUMPER UNDER COVER	Torn	425	\$880.00	✓
1SET	FRONT BUMPER UNDER COVER CLIPS	ner	45	\$60.00	✓
1PC	FRONT FOG LAMP N/S	n1		\$520.00	X
1PC	FRONT FOG LAMP GARNISH N/S	320/m-s	282	\$335.00	✓
1PC	FRONT GRILLE ASSY	cre	1754	\$1,880.00	✓
1PC	FRONT GRILLE LOGO	^^		\$105.00	X
1SET	FRONT GRILLE PARKING CAMERA	^^		\$1,850.00	X
2PCS	HEADLAMPS @\$8928.00	n/s cre	8172	\$17,856.00	1PC
2PCS	HEADLAMP LOWER BRACKETS @\$890.00	n/s cre	168	\$1,780.00	1PC
1PC	HEADLAMP NOZZLE COVER N/S	tw1		\$82.00	✓
1PC	HEADLAMP NOZZLE N/S	cre	231	\$350.00	✓
1PC	FRONT AIR GUIDE TOP N/S	Torn		\$98.00	✓
2PCS	FRONT AIR GUIDES @\$ 430.00	n/s Torn	200	\$870.00	1PC
1PC	FRONT SUPPORT PANEL TOP COVER	Dis	168	\$199.00	✓
1PC	FRONT SUPPORT PANEL	cre	1127	\$1,955.00	✓
1PC	FRONT SUPPORT PANEL N/S	Burf		\$100.00	✓
1PC	FRONT SUPPORT PANEL CENTRE BRACKET	Burf	142	\$150.00	✓
1PC	AIR CON CONDENSER	Burf/tw1	880	\$1,540.10	✓
1PC	RADIATOR	^^		\$988.00	X
1PC	INTER COOLER	holder cre	1280	\$1,450.00	✓
1PC	FRONT BRACE PANEL	tw1	366	\$885.00	✓
1PC	FRONT FENDER N/S	BuL	1227	\$1,200.00	✓
1PC	FRONT FENDER INNER SHIELD N/S	Torn	282	\$313.00	✓
1PC	FRONT FENDER INNER SHIELD CLIPS N/S	ner		\$50.00	✓
1PC	FRONT DOOR N/S	R		\$2,880.00	X
1PC	TEMPERATURE SENSOR	cre		\$188.00	✓
1SET	FRONT BUMPER CLIPS	ner		\$80.00	✓

157

60

25768

1PC FRONT LICENCE PLATE W/HOLDER
 1BOL AIR CON OIL
 1BOL RADIATOR COOLANT

*but
 new
 new*

\$150.00 20 5/2
 \$50.00 30 5/2
 \$50.00 30 5/2
 \$52,558.10

TO CHECK WIRING
 TO REFILL AIR CON GAS
 TO SPRAY RUST PROOFING
 TO RESET DIAGNOSTIC & REPROGRAMME SYSTEM
 LABOUR FOR PANEL BEATING & REPLACED PARTS
 TO PUTTY & SPRAY PAINTING

\$50.00 20
 \$120.00 100
 \$100.00 60
 \$580.00 60
 \$1,200.00 800
 \$1,800.00 950
 TOTAL \$56,408.10

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-25768
 52
 24479.60
 80
 1990
 26549.60
 202
 21239.