

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SML 6405J
OD/GA

M/S : GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE,
16-01 CENTENNIAL TOWER
SINGAPORE 039190

TEL: 68046037 FAX: 62353354
ATTN: Motor Claim Department

WS Ref: OD/GA
Claim Type: Own Damage
Accident Date: 16/09/2022


Claim No: ES2290957
Estimate No: ES2290957/YISHUN
Date: 20 Sep 2022
Policy No: MT20211455
Veh Reg No: SML6405J
Make/Model: TOYOTA TOYOTA
NOAH 2.0X CVT
Chassis No: ZRR800398038
Engine No: 3ZRC243525
Reg. Date: 18/05/2018

Estimate Repair Cost to Vehicle No : SML6405J

Description	U/Price	Quantity	Cost S\$	Amount S\$
Cost Plus				
1 FRONT BUMPER	280.00	1 PC	280.00 <i>add</i>	
2 FRONT BUMPER RH SIDE RETAINER	45.00	1 PC	45.00 <i>xsv</i>	
3 FRONT BUMPER RH FOG LAMP GARNISH	70.00	1 PC	70.00 <i>vms</i>	
4 FRONT BUMPER CLIPS	2.00	6 PCS	12.00 <i>vnc</i>	
5 RH HEADLAMP	980.00	1 PC	980.00 <i>vgr</i>	
6 FRONT RH FENDER	350.00	1 PC	350.00 <i>xr</i>	
7 FRONT RH FENDER INNER SHIELD	95.00	1 PC	95.00 <i>xnn</i>	
8 FRONT RH FENDER INNER SHIELD CLIPS	2.00	6 PCS	12.00 <i>xnn</i>	
9 RH HEADLAMP PROTECTOR	70.00	1 PC	70.00 <i>vnt</i>	
			1,914.00	
	Add 10%		191.40	2,105.40
10 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMP, FRT RH FENDER, TO KNOCK & REPAIR FRT LH FENDER INNER PANEL, FRT SUPPORT PANEL	500.00	1 LA	500.00 <i>400</i>	
11 PUTTY & RESPRAY FRT RH DOOR, FENDER, FRT BUMPER, FRT RH FENDER INNER PANEL AND ALL AFFECTED AREAS	700.00	1 LA	700.00 <i>500</i>	
				1,200.00
Total			S\$ 3,305.40	
Add GST @ 7%			231.38	
Total Amount payable			S\$ 3,536.78	

*P/P
4 days*

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE