9/27/22, 4:57 PM

Plate
Number
SDQ971K

Case Number
Toyota

Brand
Toyota

Model
Body
Insurance company
India International
Insurance
Sedan
Insurance

Technician SA Parts Manager

- LKK_assignments -

No data

Remarks 1 remarks

2022-09-27 16:53 Assessor Supervisor-Insurlogic 1 6584981566

Pre Review done base on survey information provided Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Pre Review By : Insurlogic

Amount: \$4169.05 Check: \$308.10

Repair Duration: 6 days